



# Goldy Precision Stampings

<b>Process</b>	520CJ00102- Dowel pin height modification.	<b>Supplier</b>	M/s Godly Precision stampings Pvt. Ltd.
		<b>Improved date</b>	22.04.2022

<b>BEFORE</b>	<b>AFTER</b>
---------------	--------------



<b>Problem</b>	Blanking Tool- Dowel pin not ok, dowel pin height in sufficient	<b>Improvement</b>	Blanking Tool- Dowel pin height increase more than 2 mm of thickness. (Height increase 3.5 against 1.5mm)
----------------	-----------------------------------------------------------------	--------------------	-----------------------------------------------------------------------------------------------------------