





# Work Instruction Manual

## Check Points:

Theme **Grinding Machine Remain spring Check Map**

1. At the start of the work, or while taking lot for Painting, Confirm according to number order whether there is a remaining spring or not.
2. If a remain spring is found, record the number of the remain point and put it in a red box.
3. After the completion of work, arrange the work desk in such a way that there is no remained spring.



Document No.		4					Approved	Check	Make
		3							
		2							
		1	10.3.2022						
NACI	Rev No.	Date	Revision History	Approved	Check	Make			