

ONE POINT LESSON

Problem	Lug Broken due to Hairline Crack	Occ.	New
Cust. Comp.	Customer Complaint	OPL NO	DC/OPL-17
Part Name	Outer tube 9080	Month	Dec-22
<input checked="" type="checkbox"/> In house Problem	<input type="checkbox"/> Customer complaint	<input type="checkbox"/> Improvement Idea	

100% MARKING AT COUNTER IN VMC Q-GATE

RESP.
Pushpa Singh
Kavita Dabhade
Kulkarni

NOT OK



Reject This type of Hairline Crack Part

OK



Accept No hairline crack mark part

Training Date											
Done By											
Received By											

Prepared By Shrinivas

Approved By Ashok Doifode