


Occurrence_E11 marking instead of E4

Occurrence :E11 part program removed from regular printing machine and moved to separate line , Regular Two wheeler parts and CVDP will not be done in same line

Before



After

