


Out flow_ **E11** marking instead of E4

Outflow :100% inspection will be done using vision system to ensure the presence of correct E4 Marking on the part

Before



After



Vision Machine