



ON JOB TRAINING

Part no: Outer tube BUPE-LH-KOLA, Date: 27/9/2023

Part Name: PBR 04316.M, Venue: Shop - Floor.

Issue:- mix-up. other MODEL.

| Sr.No. | Training given for | Operator Name | Sign | Effectiveness |
|--------|---|------------------|----------|-----------------|
| 1. | product knowledge | Manish Kumar | Manish | Able to perform |
| 2. | Process flow. | Archeana Harvate | Archeana | |
| 3. | customer complaint awareness. | Krishna | Krishna | |
| 4. | awareness about part mix-up issue in KOLA | Balaji. | Balaji | |
| | | Ravi. | Ravi | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Bhagn
Trainer