

ADVANTECH
AUTO INDUSTRY

OC. NO.

FM/QA/06

REV.

0

Insp. By

Rejected Qty

Defects

Sr No	Date	Part Name	Checked Qty	OK Qty.	Defects											Rejected Qty	Insp. By	
					N/F	B/H	SOLD	Bend	CATCHING	Dent/Da mage	PIN DEEP/pin broken	Fettling REJECTI ON	No Go	Groove Missing	6 Hole Missing			Patch Mark
1	30/09/23	CLUTCH HOUSING	385	360	1	3						5	1			5	15	Mineishi
2	02/10/23	CLUTCH HOUSING	464	440		5						2	6			11	24	Mineishi
3																		
4																		
5																		
6																		
7																		
8																		
9																		
10																		
11																		
12																		
13																		
14																		
15																		