

Format Number : SQA /053

Revision Number : 00

Revision Date : 01.02.2022

ANANT ENTERPRISES

QUALITY ALERT

QA NO :- 4

Customer	Customer Complaint No	Complaint Type	Date of Complaint
ETPL		Fitment	
Customer Location	Part Name	Qty Reported	01-02-2024
NURSA PURA	KONA OUTER TUBE RH/LH	2 nos	
Complaint Reported By	Customer Part Number		Defective Part Batch Code
ETPL	F2BF367070 / F2BF368070		
Complaint Received By			
Anant Ent.			

NOT OK PHOTO

OK PHOTO

Actual: M6X1-6H thread missing in part.

Specification: M6X1-6H thread in part



**CONTAINMENT DOT IDENTIFICATION MARK ON M6 FACE.
100 % Visual verification of M6 thread.**

Prepared By :

Approved By:

BHAGYESH K

Mallappa Belavi



ICA Identification Mark

Distribution List

WORK STATION <input checked="" type="checkbox"/>	HOD MATL <input type="checkbox"/>	Photo after dot mark	ICA details e.g.:
CC <input type="checkbox"/>	HOD PROCESS <input type="checkbox"/>		
HOD Prod <input type="checkbox"/>	HOD AE <input type="checkbox"/>		
HOD QA <input type="checkbox"/>	PLANT HEAD <input type="checkbox"/>		

Note : - This document needs to be filled, controlled & monitored by Quality Engineer.

- This document can be removed after one month of inclusion of Firewall at concerned workstation