

Final inspector not aware about pin hole defect