

**BEFORE**



**AFTER**



**AFTER1**



VMM (Camera based) inspection will be provided for 100% inspection of CTQ parameter.

**Problem Description :**  
Inspection Method Vernier Caliper not possible 100%

**Problem Description :**  
Master and Dial comparator for 100% inspection.