



DHANANJAY ENTERPRISES - I

PRE-DISPACTH INSPECTION REPORT

Part no :520JT11702	Vendor Code	100150			Contact Ph.No.:0240-6607917, 0240-6607924
	Vendor Name	DHANANJAY ENTERPRISES			Inspected By : Mr. Rohan Patti
Part Name : Plate Clutch BAL 4 Plate	Customer Name	ETL			Approved By : Mr. Nikunj Attarde
	Invoice No	SP 200084352	Inv. Date	12-06-24 SP 200084352	Designation : QA MOD
	Lot Ok Qty	20 Nos			

Sr. No.	Side Location	Ra (Surface Finish) 0.8 max.				Rpk (Surface Finish) 0.2-0.6				Planishing depth 0.15-0.20				Remark
		1	2	3	4	1	2	3	4	1	2	3	4	
1	A (Radius Side)	0.384	0.469	0.214	0.331	0.298	0.481	0.366	0.329	0.16	0.17	0.18	0.19	OK
	B (Without Radius Side)	0.239	0.287	0.596	0.692	0.339	0.276	0.487	0.302	0.17	0.15	0.16	0.18	OK
2	A (Radius Side)	0.735	0.369	0.614	0.415	0.584	1.024	0.354	0.272	0.19	0.18	0.16	0.18	OK
	B (Without Radius Side)	0.582	0.791	0.389	0.335	0.282	0.340	0.508	0.415	0.18	0.19	0.16	0.17	OK
3	A (Radius Side)	0.606	0.379	0.337	0.219	0.312	0.568	0.471	0.267	0.18	0.18	0.17	0.18	OK
	B (Without Radius Side)	0.298	0.319	0.338	0.391	0.378	0.408	0.564	0.384	0.19	0.16	0.18	0.16	OK
4	A (Radius Side)	0.524	0.601	0.352	0.264	0.412	0.302	0.351	0.261	0.17	0.16	0.17	0.19	OK
	B (Without Radius Side)	0.211	0.309	0.435	0.371	0.416	0.266	0.321	0.590	0.18	0.16	0.17	0.17	OK
5	A (Radius Side)	0.269	0.514	0.367	0.282	0.312	1.016	0.516	0.387	0.18	0.19	0.18	0.19	OK
	B (Without Radius Side)	0.314	0.321	0.434	0.412	0.338	0.442	0.309	0.384	0.16	0.16	0.17	0.18	OK
6	A (Radius Side)													
	B (Without Radius Side)													
7	A (Radius Side)													
	B (Without Radius Side)													
8	A (Radius Side)													
	B (Without Radius Side)													
9	A (Radius Side)													
	B (Without Radius Side)													
10	A (Radius Side)													
	B (Without Radius Side)													

Attarde