

ACTION EVIDENCIES---Occurrence

BEFORE



CNC Machine Spindle Bearing Wear out

AFTER



New Bearing Replacement Done

