

Not OK



CD not Ok

OK



100% part checking started by  
relation gauge at final stage