



**MINUTES OF THE MEETING**

VENUE: ETL-K120

SUPPLIER: M/s Bwestar

DATE: 11/06/2022

**ETL REPRESENTATIVE :**

1. Mr. Sanil Bhatnagar *[Signature]*
2. Sunil Mogal *[Signature]*
3. *[Signature]*

**PARTY'S REPRESENTATIVE**

1. Sarang Chandak *[Signature]*
- 2.
- 3.

PROBLEM / DEFFECT OBSERVED	REASON	CORRECTIVE & PREVENTIVE ACTION AT SUPPLIER END	TARGET DATE	REMARKS
<p>1) In received lot of spacer tube 7702 observed with excess gate mark concern of resting face. total four parts found during HQ parts analysis.</p> <p>2) During dimensional inspection face parallelism observed upto 0.3 mm against drg requirement of 0.1 mm.</p> <p>Such deviation affecting assembly function.</p> <p>Hence we are rejecting available stock qty as it is.</p>		<p>1) Will take corrective action after discussion with mangement.</p>		