

Check List for Welding Machin, Grander, Drill Machine Hot Air Gun, Electric Hot Plate & Chpsa Machine		
	Date of Checking : 15/08/2022	OK / Not Ok
1	Machine Name : - Welding Machin, Grander, Drill Machine Hot Air Gun, & Chpsa Machine	Ok
2	Insure that there is no joint for cable.	Ok
3	Insure that there is ELCB rating is as per safety instruction.	Ok
4	Insure that there is top Pin available for equipment.	Ok
5	Insure that there is earthling completed for equipments.	Ok
6	Ensure that cable is not lying in man movement area.	Ok
7	Ensure that switch button is in good working of equipment.	Ok
8	Ensure that safety guard is fitted to equipment.	Ok
9	Ensure that cooling fan is in working	Ok
10	To be check equipment is fully covered body	Ok

For Shree Ganesh Enterprises

Kuber Rajkumar

Mob : 8888867016

*Kuber Rajkumar*  
15/08/2022