RAJNANDANI ENTERPRISES

Industrial Multi Services Provider

Service Type: All Type Fabrication Mfg.Civil/Fab Maintainance, All Scrap, Man Power, Painting, Transports, etc.

Add: MILKAT NUMBER: 10450, Road: Dattanagar, Ranjangaon SP, Aurangabad-431136

Mob.: 8459081508 / 9637347073, E-Mail: rajnandanienterprises84@gmail.com

METHOD STATEMENT

- 1. Firstly check the power is OFF or not on which we have to do work. If it is ON, then OFF the equipment / machine / panel/ etc. before starting the work.
- 2. Put LOTO on it.
- 3. Wear all PPE's i.e. helmet, gloves, etc.
- 4. Start the work with all properly checked tools.
- 5. After completing the work check properly the equipment that no any tool left in it & clean the equipment properly.
- 6. After that inform the authorized to recheck the equipment.
- 7. After all necessary checking from the authorities, with their permission pull out the LOTO.
- 8. In presence of concerned person & with their permission, start the equipment.
- 9. As the equipment start check all necessary measures, if all is ok then make the site clear & clean.

