

Y S ENGINEERING

Mfg of : Dies, Hydraulic Fixtures, All Machine Maintenance, Other Comp. of Dies

Add : Plot No.17, Gut No.71, Wadgaon(Ko),MIDC Waluj,Aurangabad-431136.

Email : ysengineering@rediffmail.com, Mob : 9552366855

Ref No :

Date :

METHOD STATEMENT FOR FABRICATION WORK

A				
Job Description : Repair of machine spare and machine modification and all types of maintenance				
Area/ Location : Plant-				
Aux Permit Type :		General work, mechanical work		
B				
Major hazards associated with the job:				
1	Electric Shock		5	
2	Fire and Explosion			
3	Slip, Trip and Fall Hazard			
4	Falling Object			
What Worst can Happen?				
1	Fatality or permanent disability due to Electric Shock , etc			
C				
PPE's Required for Jobs: Safety Shoes, Safety Glasses, Hand Gloves, Welding apron				
Resources/ Tools Required for the Job : Electrical Tools grinder, Drill machine lathe machine, grinding machine milling machine and CMC				
Activities sequences: (What , who & How?)				
Sr. no	Activity	Who Will do	Risk Involved	Risk Mitigation/Control Measure
1	Take Work Permit	Executor will take the permit signed by respective authorities	Nil	Full Compliance to PTW Process

