

## How to achieve handling of equipment in good condition

1. Do not use any equipment unless you understand its operation.
2. Use all guards and safety devices on equipment. Set grinding machines at zero (blade closed) when not in use.
3. Don't touch or remove any kind of equipment while it is running, not even with a grinding wheel.
4. Unplug electric equipment before disassembling or cleaning.
5. Make sure the switch is off before plugging in equipment.
6. Do not touch or handle electric equipment, including switches, if your hands are wet or if you are standing in water.
7. Wear properly fitting clothing and tuck in apron strings to avoid getting them caught in machinery.
8. Use equipment only for the purpose intended.
9. small machinery and other equipment properly on equipment racks so they are stable and not likely to fall.

