

Doc No - 10/22

Rev No - -

Rev. Date - -

### DAILY CHECK LIST

- Responsibility**
- Normal Condition
  - Can Run But Not Corrected
  - Ok After Correction
  - Immediate Action Needed ( Safety )

Machine Name: Shot Blasting -  
 Location: Shirapur  
 Month: OCTOBER-22  
 Checking Time: 8:30 Am Daily

No	Check Points	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31
1	Machine Cleaning From All Side	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2	Leakage Of Shot From Any Point	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
3	Check Indexing Operation	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
4	Any Avabnormal Noise During Machine Running	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
5	Check Function Shot Controlle Valve Pneumatic	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
6	Check Rotor Motor Current	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
7	Check Emergncy Button Operation	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
8	Check Pannel Door Lock	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
9	Dust Cleening Once A day From Dust Collector	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
10	Daily Shot Filling in Machine	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	
Done By		1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31

Verified By:




**Step : 1**  
 सब से पहले शॉट व्वास्त मशीन को Main Switch से ऑन करे




**Step : 2**  
 अब साइकिल टाइम डाले ( 8 min.)




**Step : 3**  
 DUST COLLECTOR & ELEVATOR स्विच ऑन करे



**Step : 4**  
 अब हैंगर पर कास्टिंग को हैंग करे ( 32 Pcs. ) और मशीन के अंदर टक्केले



**Step : 5**  
 अब शॉट व्वास्त मशीन को ऑटो में चलाने के लिए पहले ऑटो स्विच सेलेक्ट करे और फिर ऑटो वाले बटन को दबाये



शॉट व्वास्टिंग के समय सेफ्टी गॉगल ,कानों के लिए प्लग , दस्ताने और नोज मास्क अवश्य पहने .

मशीन की सफाई के दौरान Main Switch बन्द रखे

आपतकालीन स्थिति में EMERGENCY स्विच को दबाये



**Step : 6**  
 स्टीत शॉट्स की मात्रा चेक करे , IMPELLER 1 & 2 AMPERE की रीडिंग ( 8-10 ) होनी चाहिए

**Step : 7**  
 साइकिल टाइम के कम्प्लीट होने का इंतज़ार करे

**Step : 8**  
 डोर खोले और हैंगर को बाहर निकाले

**Step : 9**  
 फिर कास्टिंग की शॉट व्वास्टिंग क्वालिटी Visual चेक करे, कास्टिंग में से शॉट्स निकाले और कास्टिंग को पीली टूली रख के क्वालिटी को ऑफर करे

PREPARED BY: *[Signature]*

CHECKED BY: *[Signature]*

APPROVED BY: *[Signature]*



**TRAINING ATTENDANCE SHEET**

PROGRAM TITLE:-		TRAINING ABOUT SHOT BLASTING MACHINE			
FACULTY:-		SANJAY SINGH	VENUE:-		AURANGABAD
DATE:-		12-10-2022	DURATION:-		30 MIN.
SR. NO.	EMPLOYEE CODE	NAME OF EMPLOYEE	DEPARTMENT	DESIGNATION	SIGNATURE
1	ST00125	SALMAN TADVI	SHOT BLASTING	SUPERWISER	<i>Salman</i>
2	ST00129	DAULAT MAHAJAN	SHOT BLASTING	OPERATOR	<i>Daulat</i>
3	ST00130	RASHID TADVI	SHOT BLASTING	HELPER	<i>R. Tadvi</i>
4	ST00167	JAYRAM CHAUHAN	SHOT BLASTING	OPERATOR	<i>Jayram Chauhan</i>
5	ST00189	ASHOK KUMAR	SHOT BLASTING	HELPER	<i>Ashok R</i>
6	ST00204	RAHUL KUMAR	SHOT BLASTING	OPERATOR	<i>Rahul Kumar</i>
7	ST00234	JITENDRA CHOUDHARI	SHOT BLASTING	HELPER	<i>Jitendra C.</i>
8	ST00239	ARBIND KUMAR	SHOT BLASTING	OPERATOR	<i>Arbind</i>
9	ST00246	PINKAL KUMAR	SHOT BLASTING	OPERATOR	<i>Pinkal</i>
10	ST00263	ANIL KUMAR	SHOT BLASTING	OPERATOR	<i>Anil</i>
11	ST00250	VIKAS GUDHEKAR	SHOT BLASTING	FITTER	<i>Vikas Gudhekar</i>

