MICRO ENGINEERING

ALL TYPES OF TOOL ROOM & HYDRAULIC REPAIRING, PRESS MACHINE WORK Mob. No. + 91 9822056900 Email: microengineering1968@gmail.com

SOP (Standard Operating Procedure)

- While working in Company, before work can commence, properly complete all work permits, safety induction meetings, etc.
- Our motive of company for safety is use three (Safety Shoes, Safety Helmet and Mask and carry three (Hand gloves, Safety Goggles and Ear Plugs.)
- Equipment inspections will be completed by qualified personnel.
- While working on height, insure life line or arrange life line to tie double harness safety belt.
- Establish the scope of work, and ensure everyone knows their specific job duty.
- While doing welding work the workmen should wear full welding apron. As before any work, please ensure all tools and tackles in good condition no any
- tear/cutting of wire of any equipment. As before doing FRP work in tank area ensure proper air ventilation and use PVC
- hand gloves for work. Fallow all guidelines regarding work and company policy..
- Before working on site the workmen fully insured by medical insurance.
- safety training provided to workmen.

For Micro Engineering

Address: Sai Udhyog Nagari, Gut No. 22, Plot No 1 / 2, Back Side Cosmo Film, MIDC Waluj, Aurangbad-431136