

Check List Tools & Equipment's

Air Control Solution

Date 10/03/2023

Sr No.	List Of Tools	Visual Inspection	Cable	Pin Top	Remark
		1	Screw Driver	OK	OK
2	Drill Machine	OK	OK	OK	OK
3	Welding Machine	OK	OK	OK	OK
4	Cutting Set	OK	OK	OK	OK
5	Grinder	OK	OK	OK	OK
6	Plier	OK	OK	OK	OK
7	Pipe Bender	OK	OK	OK	OK

Air Control Solution

Date 10/03/2023

Check By:



Sign

No.	Visual Inspection	Cable	Pin Top	Remark
1	Screw Driver			
2	Drill Machine			
3	Welding Machine			
4	Cutting Set			
5	Grinder			
6	Plier			
7	Pipe Bender			

Check By: