



SAMARTH ENGINEERING SERVICES

Structural Fabrication | Roofing Services | Civil & FRP

Email: samarthengineering.serv@gmail.com

Mob. No. + 91 9767678295

HAZARD IDENTIFICATION AND RISK ASSEMENT (HIRA)

Hazard Identification And Risk Assessment (HIRA)			
<u>Sr. No.</u>	<u>Activity</u>	<u>Hazard</u>	<u>Control Measure</u>
1)	Welding Work	Hand Injury	Used Full Body Leather Apron
		Eye Injury	Used Full Face Welding Shield
		Electric Shock	Used Pin Top and No Wire Cut to the cables
2)	Gas Cutting Work	Hand Injury	Used Leather Hand gloves while material cutting
		Eye Injury	Used Safety Goggles
3)	FRP Work	Hand Injury	Used PVC Hand Gloves while working
		Eye Injury	Used Transparent Goggles for Eye Irritation
4)	Roof Sheeting Work	Fall From Height	1) Used Double Harness Safety Belt 2) Ensure Lifeline Before start the Roof Work or Make Provision of Lifeline 3) Used Helmet while working on Height.

For Samarth Engineering Services



Office and Factory Address: H-50, MIDC Waluj, Aurangabad-431136