

AFTER



Remark : one metal sheet welded here and creat slope hence now no any material collect here.