

Improvement Action:

Before

Curing defect was not defined in matrix at final stage

After

Visual defect matrix updated for curing at dust lip at final inspection stage.