
WELCOME TO ACTION TAKEN TO AVOID BLOW HOLE IN TVS MASTER CYLINDER

Action plan- Slits provided in die of TVS master cylinder to avoid blow hole



Thank you