

POWDER COATING DEFECT MATRIX



SCRAATCH- INHW MARKS



MC AREA - POWDER DEPOSITION



DEEP PIT MARKS / DUST - LOW



DUST ON SEW ROSS



PIT MARKS / DUST - SEW ROSS



PIN HOLES / OIL PATCH



MS2 / MS - TOP SURFACE - MARK / DUST



SIDE BOSS ID - POWDER



DUST IN SIDE BOSS



SCRAATCH MARKS ON TOP FACE



UNCOVERAGE



DUST / PIT MARKS



UNCOVERAGE



DAMAGES - THREADED ZONE



UNCOVERAGE



DAMAGES



ONE TO ONE TOUCH - UNCOVERAGE



ONE TO ONE TOUCH - UNCOVERAGE



OK PART



OK PART



OK PART



OK PART

REMARK - PIT MARKS & DUST @ BACK SIDE OK, NO DAMAGES, SCRAATCHS ALLOWED THRU OUT UNDER BSK, UNWORN TOUCHUP AND POWDER MARKS NOT ALLOWED THRU OUT UNDER BSK.

LEGENDS

NOT OK

OK