

# ONE POINT LESSON


Shop:- Final inspection

Machine:-

Class	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	Lesson no	01
	Basic knowledge	Improvement class	Trouble shooting class	Date of preparation	10.06.2023
				TPM leader	
				Section leader	PANKAJ


Topic:- ID Thread Missing

NOT OK:- ID Thread Not Ok -Threading Undersize



Before : - Sampling Inspection at Final Stage.

OK PART:- ID Threading OK part.



After:- 100% inspection at final inspection Stage by Thread Plug Gauge

Key Points:- ID Threading Not Ok- Threading Undersize

Know Why:- To ensure defect free parts supply to customer.

Date	10.06.2023	12.06.2023	13.06.2023	14.06.2023	15.06.2023		
Teacher	Pankaj	Sagar	Sagar	Sagar	Shaikh		
Learner	Sagar	Sunita	Gaikwad	Shaikh	Surwase		