

















Skill Matrix for Associates (Visual inspection)													
Able to train or lead				Can perform task									
Incompetent				Able to job under supervision									
Latest review on:- JAN-2024				Latest review on:- JULY-2024									
Sr.No.	Photo	Associate Name	Customer name	Status	SKILLS								
			Part name		Visual Inspection	Work instruction (SOP)	Product knowledge	Rework Parts Handling	OK part handling	NOT OK part handling	Critical characteristics	Rejection data monitoring	Gauging
<b>ALL OUTER TUBES</b>													
1		Ravi Morya	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
2		Manish Kumar	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
3		Shyam Sundar	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
4		Sapna Murkute	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
5		Anju Gholap	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
6		Muktaram	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
7		Budhnarayan	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
8		Sakshi Lonkar	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
9		Priyanka Gupta	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
10		Kamod	GIL / Endurance All Outer tube	●	√	√	√	√	√	√	√	√	√
12		Chotu Singh	GIL / Endurance All Outer tube /bolero	◐	√	X	X	X	√	√	X	X	X
13		Kuldeep Pal	GIL / Endurance All Outer tube	◐	√	X	X	X	√	√	X	X	X
<b>HOUSING (HYDROMAX)</b>													
12		Sushila Salunke	Housing (Hydromax)	●	√	√	√	√	√	√	√	√	√
13		Sakshi Lonkar	Housing (Hydromax)	●	√	√	√	√	√	√	√	√	√
14		Vaishali	Housing (Hydromax)	●	√	√	√	√	√	√	√	NA	√
15		Anju Gholap	Housing (Hydromax)	●	√	√	√	√	√	√	√	√	√
Prepared By: <i>Priyanka</i>				Verified By: <i>Shashi</i>						F/AE/HR/06 :Rev:- 0, Date:-01/04/2017			