



T
P
M

ONE POINT LESSON

Number	136
DATE	05.04.2024
Prepared by-P.SHINDE	

Theme

To prevent OD undersize parts

Classification

Basic Knowledge

Improvement

Trouble Shooting

X

✓



OD undersize due to Buffing parts

Okay part without buffing

Actual Results	Date Executed	05.04.2024					
	Trainer	Shinde					
	Trainee	All Insepction Operator					