



ANANT ENTERPRISES

Defect: Pin Hole /Blow Hole

Before



Die Coating Peel of due to touch up time more than 3hrs

After



Die touch up within 1-2hrs