No Checkpoint available in between Oxsilan bath & DM Mixture after Power Failure