

# Work Instructions for Raw Material inspection

Doc No- WI/QA/18

Rev No/Date-00/03.03.2022

Page No - 01 of 01


#### 1) Thickness inspection

As per below photo, raw material sheets to be checked for thickness at 12 locations. In case of any non conformity, material to be rejected by informing purchase department & supplier.

If tolerance in ±0.05mm in RM thick variation upto ±0.03mm then its ok.

If tolerance in ±0.10mm in RM thick variation upto ±0.05mm then its ok.

If RM thickness variation is more then matrial to be rejected.



#### 2) Visual Inspection

Visual inspection for Dent, Scratches, Rust, Pitted marks, Scales, Bend to be done from both faces of sheets. In case of any non conformity, material to be rejected by informing purchase department & supplier.

### 3) Hardness Inspection

Hardness verification of all type of Raw material to be done in inhouse hardness testing facility as per work instructions for hardness testing (WI/QA/03-00/01.01.2018). In case of any non conformity, material to be rejected by informing purchase department & supplier.

## 4) Outsource Lab Testing

For Raw material from Traders, each lot to be verified in Third party lab testing for conforming grade before starting production. Material from Mill to be verified on quarterly basis as per Raw material test plan (F/QA/23-01/01.04.21). In case of any non conformity, material to be rejected by informing purchase department & supplier.

PREPARED BY - Suraj Ghevde

APPROVED BY - Atul Nikumbh