



# HPPL- QUALITY ALERT



Doc No. :- F/QA/37  
Rev. No/ Date :- 00/01.06.2019  
Page No. :- 01 of 01

<b>PART NUMBER :</b>	520FN04002	<b>DATE</b>	31.05.2024
<b>PART NAME :</b>	Holder Clutch	<b>QUANTITY REJECTED</b>	300 Nos
<b>CUSTOMER :</b>	Endurance	<b>TOTAL DISPATCH QUANTITY</b>	300 Nos
<b>PROBLEM DESCRIPTION</b>	Bearing Resting Height found undersize & Oversize up to 2.96~3.14 mm against 3±0.1		



OK



NOT OK

PREPARED BY - KW

APPROVED BY - AN