QFR No - 8000896614

Defect Details

NC No.	8000896614
NC Date	22/10/2024
NC Submission Date	
Part No.	ASB01AM012
Part Name	ECCENTRIC
Supplier Name & Code	100505-A B AUTOCOMPONENTS
ETL Plant	1120-ETL K-226/2 Disc Brakes
Defect Details	DAMAGE-DAMAGE & MARK

1. Problem Description

Defect Description	DAMAGE-DAMAGE & MARK
Detection Stage	Inprocess
Problem Severity	Aesthetic
NG Quantity	2
Is Defect Repeatative?	No
Defect Sketch / Photo	

Supplier Communication Details

Quality Head Email ID	
Plant Head/CEO Email ID	
MD Email ID	

2. Stock Details & action taken for NG parts

Location	ETL End	Warehouse	Transit	Supplier FG	Supplier WIP	Total
Total Qty						
Check Qty						
NG Qty						

Action taken on NG part

Scrap	
Rework	
Under Deviation	

Containment Action	

- -

4. Process Details

Process / Operation	
Outsource	
Machine / Cell	
Machine / Cell No.	

5. Problem Analysis

Type Possible Cause Fact Verification	but

6. Inspection Method Analysis (Current)

Inspection Method	
Other Inspection Method	
Check Point at Final Inspection	
Checking Freq.	
Sampling	
Sample Size	

7. Root Cause Analysis (Occurance)

Why 1	
Why 2	
Why 3	
Why 4	
Why 5	
Root Cause (Occurance)	

Root Cause Analysis (Outflow)

Why 1	
Why 2	
Why 3	
Why 4	
Why 5	
Root Cause (Outflow)	

8. Countermeasure (Occurrence , Outflow & System side Actions)

Туре	Countermeasure Details	Responsibility	Target Date	Actual Date	Status	
------	------------------------	----------------	-------------	-------------	--------	--

9. Inspection Method After Customer Complaint

Change In Inspection System	
Change Details	
Inspection Method	
Other Inspection Method	
Check Point at Final Inspection	
Checking Freq.	
Sampling	
Sample Size	

10. Evidance of Countermeasure

Occurance (Before)	
Occurance (After)	
Outflow (Before)	
Outflow (After)	

11. Horizontal Deployment

12. Document Review

Documents	
Specify Other Document	it in the second s

13. Effectiveness Of Action

Reviewed Quantity	
Reason for submission	