

FORM No. 11 (See Rules 62 and 64)*(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : SHIVKRUPPA CRANE SERVICE.
- 2) Address of the Factory : At Post - Nighoje, Tal. - Khed, Dist. - Pune - 410501.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Polyester Belt. (Qty. -04 Nos.)
Sr. No. - 178, 155, 176, 118.
Length - 4.5 Mtr.
Capacity - 6.0 Ton, (Please refer load chart before lifting),
Make- Powerlift.
Location- On Site.
Mfg. Year - 2022.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found -
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 16/10/2022 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 16/10/2022, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Test Date-16/10/2022, Due Date-15/10/2023.

S. No.-2, Plot No.-256,

Indryaninagar, Bhosari,

Pune - 411 026.

Mobile - 9850600253, 8796448299.



P.N. Kulkarni
B.E. (Mech.) M.B.A
Ex. Scientist B.A.R.C.
Chartered Engineer.

FORM No. 11 (See Rules 62 and 64)*(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : SHIVKRUPPA CRANE SERVICE.
- 2) Address of the Factory : At Post - Nighoje, Tal. - Khed, Dist. - Pune - 410501.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Polyester Belt. (Qty. -04 Nos.)
Sr. No. - 178, 155, 176, 118.
Length - 4.5 Mtr.
Capacity - 6.0 Ton, (Please refer load chart before lifting),
Make- Powerlift.
Location- On Site.
Mfg. Year - 2022.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found -
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 16/10/2022 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 16/10/2022, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Test Date-16/10/2022, Due Date-15/10/2023.

S. No.-2, Plot No.-256,
Indryaninagar, Bhosari,
Pune - 411 026.
Mobile - 9850600253, 8796448299.



P.N. Kulkarni
B.E. (Mech.) M.B.A
Ex. Scientist B.A.R.C.
Chartered Engineer.

FORM No. 11 (See Rules 62 and 64)*(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : SHIVKRUPPA CRANE SERVICE.
- 2) Address of the Factory : At Post - Nighoje, Tal. - Khed, Dist. - Pune - 410501.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Polyester Belt. (Qty. -04 Nos.)
Sr. No. - 178, 155, 176, 118.
Length - 4.5 Mtr.
Capacity - 6.0 Ton, (Please refer load chart before lifting),
Make- Powerlift.
Location- On Site.
Mfg. Year - 2022.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found -
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 16/10/2022 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 16/10/2022, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Test Date-16/10/2022, Due Date-15/10/2023.

S. No.-2, Plot No.-256,
Indryaninagar, Bhosari,
Pune - 411 026.
Mobile - 9850600253, 8796448299.



P.N. Kulkarni
B.E. (Mech.) M.B.A
Ex. Scientist B.A.R.C.
Chartered Engineer.

FORM No. 11 (See Rules 62 and 64)*(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : SHIVKRUPPA CRANE SERVICE.
- 2) Address of the Factory : At Post - Nighoje, Tal. - Khed, Dist. - Pune - 410501.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Polyester Belt. (Qty. -04 Nos.)
Sr. No. - 178, 155, 176, 118.
Length - 4.5 Mtr.
Capacity - 6.0 Ton, (Please refer load chart before lifting),
Make- Powerlift.
Location- On Site.
Mfg. Year - 2022.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found -
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 16/10/2022 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 16/10/2022, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Test Date-16/10/2022, Due Date-15/10/2023.

S. No.-2, Plot No.-256,

Indryaninagar, Bhosari,

Pune - 411 026.

Mobile - 9850600253, 8796448299.



P.N. Kulkarni
B.E. (Mech.) M.B.A
Ex. Scientist B.A.R.C.
Chartered Engineer.

FORM No. 11 (See Rules 62 and 64)*(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : SHIVKRUPPA CRANE SERVICE.
- 2) Address of the Factory : At Post - Nighoje, Tal. - Khed, Dist. - Pune - 410501.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Polyester Belt. (Qty. -04 Nos.)
Sr. No. - 178, 155, 176, 118.
Length - 4.5 Mtr.
Capacity - 6.0 Ton, (Please refer load chart before lifting),
Make - Powerlift.
Location - On Site.
Mfg. Year - 2022.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found -
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 16/10/2022 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 16/10/2022, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Test Date-16/10/2022, Due Date-15/10/2023.

S. No.-2, Plot No.-256,
Indryaninagar, Bhosari,
Pune - 411 026.
Mobile - 9850600253, 8796448299.



P.N. Kulkarni
B.E. (Mech.) M.B.A
Ex. Scientist B.A.R.C.
Chartered Engineer.



THE UNION OF INDIA
MAHARASHTRA STATE MOTOR DRIVING LICENCE



DL No **MH14 20110059119**
Valid Till : **22-09-2031 (NT)**

DOI : **23-09-2011**

FORM 7
RULE 16 (2)

AUTHORISATION TO DRIVE FOLLOWING CLASS
OF VEHICLES THROUGHOUT INDIA



COV DOI
CRANE 23-09-2011



DOB : **21-07-1991** BG :

Name : **GORAKSH DATE**
S/DW of **BABAJI**
Add : **KHARABWADI, CHAKAN, TAL. KHED,**
DIST-PUNE



PIN :
Signature & ID of Issuing Authority. *Bati*
MH14 20110059119

[Signature]
Signature/Thumb
Impression of Holder