

Highway. Pumper.

MAHALAKSHMI ENGINEERING & CONSRRTUCTION PVT LTD.

Ref.No : MECPI/EHS/023/REV 0

TITLE : VEHICLE FITNESS CHECKLIST

Project: MHDC SOALPUR

Location: Site.

Date: 07/05/2023. Time: 11:30 AM.

Inspected By: Azim Sheikh.

Frequency: Weekly

SL NO	DESCRIPTION	YES	No	TARGET DATE	REMARKS
<b>A</b>					
<b>DOCUMENTS</b>					
1	Valid Driving licence	✓			
2	Registration Document	✓			
3	Fitness certificate of Vechile Driver	✓			
4	Persmission Copy of Concern Authorities/ RTO	✓			
<b>B</b>					
<b>Fitness Check</b>					
1	PUC	✓			
2	Number plate are visible.	✓			
3	Side indicators.	✓			
4	Diesel/Oil Leakage		✓		
5	Driver cabin fitted with door & Glasses.	✓			
6	Side Mirrors.	✓			
7	Brake condition.	✓			
8	Horn/Revers Horn	✓			
9	Head Light	✓			
10	Both sides Indicator	✓			
11	Safety Guard on moving parts.	✓			
<b>C</b>					
<b>Safety Precautions</b>					
1	No Flamable material in operator cabin.	✓			
2	Clearance age >18.	✓			
3	Availability of PPE's.	✓			
4	Fire Extinguisher	✓			
5	First Aid Box inside the vehicle.	✓			
<b>D</b>					
Any Other safety Observation:					

Signature : (MECPL PROJECT ENGG)

Signature:( MECPL SAFETY OFFCER-EHS)

*Maharaj*  
*Azim*

TM 1

TM Minder - 0909

MAHALAKSHMI ENGINEERING & CONSRRTUCTION PVT LTD.

Ref No: MECPL/ENG/023/05/19

Object: MHDC SOALPUR

TITLE : VEHICLE FITNESS CHECKLIST

Inspected By: Site - Azim Sheikh

Date: 07/05/2023 Time: 11:30 AM

Frequency: Weekly

NO	DESCRIPTION	YES	No	TARGET DATE	REMARKS
<b>A DOCUMENTS</b>					
1	Valid Driving licence				
2	Registration Document	✓			
3	Fitness certificate of Vechile Driver	✓			
4	Persmission Copy of Concern Authorities/ RTO	✓			
<b>B Fitness Check</b>					
1	PUC	✓			
2	Number plate are visible.	✓			
3	Side indicators.	✓			
4	Diesel/Oil Leakage	✓			
5	Driver cabin fitted with door & Glasses.		✓		
6	Side Mirrors.	✓			
7	Brake condition.	✓			
8	Horn/Revers Horn	✓			
9	Head Light	✓			
10	Both sides Indicator	✓			
11	Safety Guard on moving parts.	✓			
<b>C Safety Precautions</b>					
1	No Flamable material in operator cabin.				
2	Clearance age >18.	✓			
3	Availability of PPE's.	✓			
4	Fire Extinguisher	✓			
5	First Aid Box inside the vehicle.	✓			
6		✓			
<b>D Any Other safety Observation:</b>					

Signature : (MECPL PROJECT ENGG)

*Mahesh*

Signature: (MECPL SAFETY OFFCER-EHS)

*Azim*  
AZIM

TM mixer-gogo.

**MAHALAKSHMI ENGINEERING & CONSRRTUCTION PVT LTD.**

Ref.No : MECPL/EHS/023/REV-0

**TITLE : VEHICLE FITNESS CHECKLIST**

Project: MHDC SOALPUR

Location: Site.

Date: 01/05/2023 Time: 11:30 AM

Inspected By: Azim Sheikh

Frequency: Weekly

SL NO	DESCRIPTION	YES	No	TARGET DATE	REMARKS
<b>A</b>	<b>DOCUMENTS</b>				
1	Valid Driving licence	✓			
2	Registration Document	✓			
3	Fitness certificate of Vechile Driver	✓			
4	Persmission Copy of Concern Authorities/ RTO	✓			
<b>B</b>	<b>Fitness Check</b>				
1	PUC	✓			
2	Number plate are visible.	✓			
3	Side indicators.	✓			
4	Diesel/Oil Leakage	✓	✓		
5	Driver cabin fitted with door & Glasses.	✓			
6	Side Mirrors.	✓			
7	Brake condition.	✓			
8	Horn/Revers Horn	✓			Revers - Horn not ok
9	Head Light	✓			
10	Both sides Indicator	✓			
11	Safety Guard on moving parts.	✓			
<b>C</b>	<b>Safety Precautions</b>				
1	No Flamable material in operator cabin.	✓			
2	Clearance age >18.	✓			
3	Availability of PPE's.	✓			
4	Fire Extinguisher	✓			
5	First Aid Box inside the vehicle.	✓			
<b>D</b>	Any Other safety Observation:				

Signature : (MECPL PROJECT ENGG)

*[Signature]*

Signature: (MECPL SAFETY OFFCER-EHS)

*[Signature]*

TM Mixer - 9000

MAHALAKSHMI ENGINEERING & CONSRRTUCTION PVT LTD.

Ref.No : MECPL/EHS/023/REV-0

TITLE : VEHICLE FITNESS CHECKLIST

Project: MHDC SOALPUR

Location: Site

Date: 07/15/2023 Time: 11:30 Am

Inspected By: Azim Shukla / Abhijit Singh Thakur

Frequency: Weekly

SL NO	DESCRIPTION	YES	No	TARGET DATE	REMARKS
<b>A DOCUMENTS</b>					
1	Valid Driving licence	✓			
2	Registration Document	✓			
3	Fitness certificate of Vechile Driver	✓			
4	Permission Copy of Concern Authorities/ RTO	✓			
<b>B Fitness Check</b>					
1	PUC	✓			
2	Number plate are visible.	✓			
3	Side indicators.	✓			
4	Diesel/Oil Leakage		✓		
5	Driver cabin fitted with door & Glasses.	✓			
6	Side Mirrors.	✓			
7	Brake condition.	✓			
8	Horn/Revers Horn	✓			
9	Head Light	✓			
10	Both sides Indicator	✓			
11	Safety Guard on moving parts.	✓			
<b>C Safety Precautions</b>					
1	No Flamable material in operator cabin.	✓			
2	Clearance age >18.	✓			
3	Availability of PPE's.	✓			
4	Fire Extinguisher	✓			
5	First Aid Box inside the vehicle.	✓			
D	Any Other safety Observation:				

Signature : (MECPL PROJECT ENGG) *[Signature]*

Signature: (MECPL SAFETY OFFCER-EHS) *[Signature]*  
AZIM