

# MAHALAKSHMI ENGINEERING & CONSRTUCTION PVT LTD.

Ref.No: MECPL/EHS/NO/REV-0

## TITLE : BAR CHOPSAW MACHINE CHECKLIST

C/S. Building - 02

Project: MHDC SOLAPUR

Location: 12, 13, Building


Date: 01/07/2023  
Time: .....

Inspected By: Azim

Frequency: ~~Weekly~~ Monthly

SL NO	DESCRIPTION	Yes	No	TARGET DATE	REMARKS
1	Cutting wheel having any crack/ damage. And cutting wheels' expiry date & its RPM match with the machine RPM" has been checked.	<input checked="" type="checkbox"/>			
2	Presence of Cutting plate guard. Double earthing has been provided in m/c to avoid shock.	<input checked="" type="checkbox"/>			
3	Presence of locking system for the plate & Guard is available	<input checked="" type="checkbox"/>			
4	Presence of job clamp and its conditions ok	<input checked="" type="checkbox"/>			
5	Presence of fibre body handle and its condition is ok.	<input checked="" type="checkbox"/>			
6	Cable condition(Any cut, wear etc.) and presence of wire 03Pin Industrial top plug is ok	<input checked="" type="checkbox"/>			
7	Presence of cutting dust guard is available	<input checked="" type="checkbox"/>			

Signature : (MECPL PROJECT ENGG/ PROJECT IN CHARGE)



Signature: (MECPL SAFETY OFFICER -EHS)



