

# FORM-11

(See rules 62 and 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLES

Cert. No. MAPL/ U-III / 01/L

- 1) Name and address of factory : **M/s MARATHWADA AUTOCOMP PVT. LTD.**  
K-22/23, MIDC WALUJ, AURANGABAD.
- 2) Name and Address of the factory : As above
- 3) a) Type identification number and description of hoist lift, lifting machine, chains and lifting tackles. : \* **Description** : Chain Pulley Block  
\* **Capacity** : 1.0 Ton.  
\* **Sr. No.** : CO 6532  
\* **Make** : M/s Indef P  
\* **Location** : Shop Floor  
: Dec-2012
- b) Date of Construction or reconstruction and the date when the hoist, lift, lifting machine chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of last examination made under section 28 (1) (a) (ii) & 29 (1) (a) (iii) by whom it was carried out : Previously tested by us on 02-12-2021
- 5) A) Maintenance: (List of parts, if any, which were Inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? : Not applicable  
If not, State what working defects have been found : ---  
(a) Enclosure of hoistway or liftway. : ---  
(b) Landing gates and case gate(s) : ---  
(c) Interlocks on the landing gates and cage gates(s) : ---  
(d) Other gates fastenings. : ---  
(e) Cage and platform and fittings. Cage guides, buffers Interior of the hoistway or liftway. : ---  
(f) Overrunning devices. : ---  
(g) Suspension ropes or chains and their attachments. : ---  
(h) Safety gear i.e. arrangements for preventing fall of Platform or cage brakes. : ---  
(i) Brakes : ---  
(j) Work of spur gearing : ---  
(k) Other electrical equipment : ---  
(l) Other parts : ---
- (B) Date and number of the certificates relating to any test and examination made under sub-rule(1) of rule 64 together with the name of the person who issued the cert : Done by Manufacturer
- (C) i) Date of annealing or their heat treatment of the chain and Lifting tackle carried out under sub-rule (5) Of rule 64 and by who it was carried out. : Not Applicable  
ii) Particulars of any defect found at any such examination Or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil
- 6) Repairs, renewals or alterations (if any) required and the Period within which they should be executed and maximum Safe working load subject to repairs, renewals or alternation (if any) : 1) The Equipment is to be maintained and operated under safe working condition.

I certify that On **01/12/2022** I thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations / tests carried out is enclosed herewith that the above is correct report of the result.

**Due Date :- 01/12/2023**

Address: -

**CHARTERED TECHNO SERVICES**  
D- WING - A, FIRST FLOOR,  
BHARAT BAZAR, API CORNER,  
AURANGABAD. 431 006  
**Phone :-9823225350**



*Prakash C Gothi*

**(PRAKASH C GOTH)**

B.E.Mech. (Hons) MIE, FIV, MIIE, FIMM.  
CHARTERED ENGINEER & COMPETENT PERSON.  
**C.P.C. NO.- MS/DISH/CPC/ P-040/2020**  
**Validity upto : 31/12/2022**



# FORM-11

(See rules 62 and 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLES

Cert. No. MAPL/ U-III / 02/L

- 1) Name and address of factory : **M/s MARATHWADA AUTOCOMP PVT. LTD.**  
K-22/23, MIDC WALUJ, AURANGABAD.
- 2) Name and Address of the factory : As above
- 3) a) Type identification number and description of hoist lift, lifting machine, chains and lifting tackles. : \* **Description** : Monorail Trolley  
\* **Capacity** : 1.0 Ton.  
\* **Sr. No.** : KC 2966  
\* **Make** : M/s Indef M  
\* **Location** : Shop Floor  
: Dec-2012
- b) Date of Construction or reconstruction and the date when the hoist, lift, lifting machine chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of last examination made under section 28 (1) (a) (ii) & 29 (1) (a) (iii) by whom it was carried out : Previously tested by us on 02-12-2021
- 5) A) Maintenance: (List of parts, if any, which were Inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? : Not applicable  
If not, State what working defects have been found : ---  
(a) Enclosure of hoistway or liftway. : ---  
(b) Landing gates and case gate(s) : ---  
(c) Interlocks on the landing gates and cage gates(s) : ---  
(d) Other gates fastenings. : ---  
(e) Cage and platform and fittings. Cage guides, buffers Interior of the hoistway or liftway. : ---  
(f) Overrunning devices. : ---  
(g) Suspension ropes or chains and their attachments. : ---  
(h) Safety gear i.e. arrangements for preventing fall of Platform or cage brakes. : ---  
(i) Brakes : ---  
(j) Work of spur gearing : ---  
(k) Other electrical equipment : ---  
(l) Other parts : ---
- (B) Date and number of the certificates relating to any test and examination made under sub-rule(1) of rule 64 together with the name of the person who issued the cert : Done by Manufacturer
- (C) i) Date of annealing or their heat treatment of the chain and Lifting tackle carried out under sub-rule (5) Of rule 64 and by who it was carried out. : Not Applicable  
ii) Particulars of any defect found at any such examination Or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil
- 6) Repairs, renewals or alterations (if any) required and the Period within which they should be executed and maximum Safe working load subject to repairs, renewals or alternation (if any) : 1) The Equipment is to be maintained and operated under safe working condition.

I certify that On **01/12/2022** I thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations / tests carried out is enclosed herewith that the above is correct report of the result.

Due Date :- 01/12/2023

Address: -

**CHARTERED TECHNO SERVICES**  
D- WING - A, FIRST FLOOR,  
BHARAT BAZAR, API CORNER,  
AURANGABAD. 431 006  
Phone :-9823225350



**(PRAKASH C GO THI)**

B.E.Mech. (Hons) MIE, FIV, MIIE, FIMM.  
CHARTERED ENGINEER & COMPETENT PERSON.  
C.P.C. NO.- MS/DISH/CPC/ P-040/2020  
Validity upto : 31/12/2022



# FORM-11

(See rules 62 and 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLES

Cert. No. MAPL/ U-III / 03/L

- 1) Name and address of factory : **M/s MARATHWADA AUTOCOMP PVT. LTD.**  
K-22/23, MIDC WALUJ, AURANGABAD.
- 2) Name and Address of the factory : As above
- 3) a) Type identification number and description of hoist lift, lifting machine, chains and lifting tackles. : \* **Description** : Pneumatic Hoist  
\* **Sr. No.** : MAPL/PH-03(4273)  
\* **Capacity** : 09 Kg  
\* **Make** : M/s Endo Kogyo Co. Ltd.  
\* **Location** : Welding Robot Line  
: 2020
- b) Date of Construction or reconstruction and the date when the hoist, lift, lifting machine chains, ropes and lifting tackles were first taken into use in the factory
- 4) Date of last examination made under section 28 (1) (a) (ii) & 29 (1) (a) (iii) by whom it was carried out : Previously tested by us on 02-12-2021
- 5) A) Maintenance: (List of parts, if any, which were Inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? : Not applicable  
If not, State what working defects have been found : ---  
(a) Enclosure of hoistway or liftway. : ---  
(b) Landing gates and case gate(s) : ---  
(c) Interlocks on the landing gates and cage gates(s) : ---  
(d) Other gates fastenings. : ---  
(e) Cage and platform and fittings. Cage guides, buffers Interior of the hoistway or liftway. : ---  
(f) Overrunning devices. : ---  
(g) Suspension ropes or chains and their attachments. : ---  
(h) Safety gear i.e. arrangements for preventing fall of Platform or cage brakes. : ---  
(i) Brakes : ---  
(j) Work of spur gearing : ---  
(k) Other electrical equipment : ---  
(l) Other parts : ---
- (B) Date and number of the certificates relating to any test and examination made under sub-rule(1) of rule 64 together with the name of the person who issued the cert : Done by Manufacturer
- (C) i) Date of annealing or their heat treatment of the chain and Lifting tackle carried out under sub-rule (5) Of rule 64 and by who it was carried out. : Not Applicable  
ii) Particulars of any defect found at any such examination Or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil
- 6) Repairs, renewals or alterations (if any) required and the Period within which they should be executed and maximum Safe working load subject to repairs, renewals or alternation (if any) : 1) The Equipment is to be operated and maintained under safe working conditions only.

I certify that On **01/12/2022** I thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations / tests carried out is enclosed herewith that the above is correct report of the result.

**Due Date :- 01/12/2023**

Address: -

**CHARTERED TECHNO SERVICES**

D- WING - A, FIRST FLOOR,  
BHARAT BAZAR, API CORNER,  
AURANGABAD. 431 006

**Phone :-9823225350**



**(PRAKASH C GOTHI)**

B.E.Mech. (Hons) MIE, FIV, MIIE, FIMM.  
CHARTERED ENGINEER & COMPETENT PERSON.  
**C.P.C. NO.- MS/DISH/CPC/ P-040/2020**  
**Validity upto : 31/12/2022**



# FORM-11

(See rules 62 and 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLES

Cert. No. MAPL/ U-III / 04/L

- 1) Name and address of factory : **M/s MARATHWADA AUTOCOMP PVT. LTD.**  
K-22/23, MIDC WALUJ, AURANGABAD.
- 2) Name and Address of the factory : As above
- 3) a) Type identification number and description of hoist lift, lifting machine, chains and lifting tackles. : \* **Description** : Scissor Lift  
\* **Sr. No.** : 01  
\* **Capacity** : 2.0 Ton  
\* **Make** : M/s Om Sai Engg  
\* **Location** : Near Store  
b) Date of Construction or reconstruction and the date when the hoist, lift, lifting machine chains, ropes and lifting tackles were first taken into use in the factory : 31/01/2021
- 4) Date of last examination made under section 28 (1) (a) (ii) & 29 (1) (a) (iii) by whom it was carried out : First Time Tested
- 5) A) Maintenance: (List of parts, if any, which were Inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? If not, State what working defects have been found : Not applicable  
(a) Enclosure of hoistway or liftway. : ---  
(b) Landing gates and case gate(s) : ---  
(c) Interlocks on the landing gates and cage gates(s) : ---  
(d) Other gates fastenings. : ---  
(e) Cage and platform and fittings. Cage guides, buffers Interior of the hoistway or liftway. : ---  
(f) Overrunning devices. : ---  
(g) Suspension ropes or chains and their attachments. : ---  
(h) Safety gear i.e. arrangements for preventing fall of Platform or cage brakes. : ---  
(i) Brakes : ---  
(j) Work of spur gearing : ---  
(k) Other electrical equipment : ---  
(l) Other parts : ---  
(B) Date and number of the certificates relating to any test and examination made under sub-rule(1) of rule 64 together with the name of the person who issued the cert : Done by Manufacturer  
(C) i) Date of annealing or their heat treatment of the chain and Lifting tackle carried out under sub-rule (5) Of rule 64 and by who it was carried out. : Not Applicable  
ii) Particulars of any defect found at any such examination Or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Safe Working Load 2.0 Ton  
: Nil
- 6) Repairs, renewals or alterations (if any) required and the Period within which they should be executed and maximum Safe working load subject to repairs, renewals or alternation (if any) : 1) The Equipment is to be operated and maintained under safe working conditions only.

I certify that On **25/03/2023** I thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations / tests carried out is enclosed herewith that the above is correct report of the result.

**Due Date :- 25/03/2024**

Address: -

**CHARTERED TECHNO SERVICES**

D- WING - A, FIRST FLOOR,  
BHARAT BAZAR, API CORNER,  
AURANGABAD. 431 006

**Phone :-9823225350**



**(PRAKASH C GOTHI)**

B.E.Mech. (Hons) MIE, FIV, MIIE, FIMM.  
CHARTERED ENGINEER & COMPETENT PERSON.  
**C.P.C. NO.- MS/DISH/CPC/ G-051/2023**  
**Validity upto : 31/12/2025**