



JEMKON PVT. LTD.

CORPORATE OFFICE: Plot No 1, Survey No. 795/2 Opp Mahindra, Subhashwadi, Nighoje-Talwade Road Nighoje, Dist - Pune, (Maharashtra) -410 501, India CIN:U24233PN2013PTC146703

Tel: 02135 - 202901 E Mail: info@jemkon.com Website: www.jemkon.com GST NO: 27AADCJ0607Q1ZC

JEMKON

ISO 9001:2008

RISK ASSESSMENT-Risk assessment is the identification of hazards that could negatively impact an organization's ability to conduct business. These assessments **help identify these inherent business risks and provide measures, processes and controls to reduce the impact of these risks to business operations.**

| Risk Assessment | | | | |
|---|---|---|---|--|
| Name | JEMKON PRIVATE LIMITED | | | |
| Department where work is to be done | In side plant | | | |
| Description of Job | Epoxy and Pu flooring work in plant area . | | | |
| | | | | |
| Activities (List of Key Components of the job) | Activity | Hazard | Risk | Control |
| | 1) Removal of existing damaged Flooring and doing epoxy and pu flooring | 1) Cuts & crush during removal of existing floor and mixing of material of epoxy and Pu material. | 1) Injuries to person due to removal of and surface preparation of existing floor for the work. | 1) USE -appropriate PPE to avoid the risk |
| Key Equipment | Name of equipment | | | |
| | Grinder, Drill machine, Cutting machine, Mixing machine | | | |
| Location | Plant area | | | |
| Expected duration of work | 50 days | | | |
| Any Other information relevant to the job. | N/A | | | |
| Specialist Skills | Nature of activities | Type of skilled required | | No of persons |
| | Installation of new false flooring. | Having experience of installation of false flooring. | | DEPEND ON THE AREA ALLOTTED, APPROX 8 TO 10 PERSON IN ONE TEA, |
| | | | | |
| | | | | |

