



# PARTH INDUSTRIES

GUT NO 48, PLOT NO 18, BEHIND ETL PLANT 1, MIDC WALUJ, AURANGBAD.

Mob No :- 8975596100

Date – 12.09.2022

To,

Endurance Technologies Ltd.

Safety Dept.

MIDC Waluj, Aurangabad – 431136

Dear Sir

We compliant with the safety requirements of equipment and we check that all the equipment is in good condition before starting the work; such as damaged cables, no loose connections, equipped with 3 pin top

### **Controlling Hazards: Safe Work Environment**

In order to control hazards, you must first create a safe work environment, then work in a safe manner. Generally, it is best to remove the hazards altogether and create an environment that is truly safe. When OSHA regulations and the NEC are followed, safe work environments are created.

But, you never know when materials or equipment might fail. Prepare yourself for the unexpected by using safe work practices. Use as many safeguards as possible. If one fails, another may protect you from injury or death.

For, Parth Industries

