

**FORM No. 11 (See Rules 62 and 64)***(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : M/S. OM DIESEL SERVICES
- 2) Address of the Factory : Ishwar kruppa Nivas, Kesnand Road, Balaji Park, Wagholi, Tal. – Haveli, Dist. – Pune – 412 207.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Fork Lift  
Reg. No. – MH 12 EB 928  
Chassis No. – H09155047  
Engine No. – A11936.,  
Capacity.- 3.0 Ton, ( Please refer load chart before lifting), Make – VOLTAS.  
**Location- On Site.**
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory : Mfg. Year – 2010.
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found:-
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate : 14/04/2023 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 14/04/2023, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

**Test Date-14/04/2023, Due Date-13/04/2024.**

S. No.-2, Plot No.-256,  
Indryaninagar, Bhosari ,  
Pune – 411 026,  
Mobile – 9850600253,8796448299.



P.N. Kulkarni  
B.E. (Mech.) M.B.A.  
Ex. Scientist B.A.R.C.  
Chartered Engineer.


**FORM No. 11 (See Rules 62 and 64)***(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : M/S. OM DIESEL SERVICES
- 2) Address of the Factory : Ishwar kruppa Nivas, Kesnand Road, Balaji Park, Wagholi, Tal. – Haveli, Dist. – Pune – 412 207.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Fork Lift  
Reg. No. – MH 06 T 3653  
Chassis No. – 150387  
Engine No. – S433060359.,  
Capacity.- 3.0 Ton, ( Please refer load chart before lifting), Make – VOLTAS.  
**Location- On Site.**
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory : Mfg. Year – 2002.
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found:-
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate. : 14/04/2023 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 14/04/2023, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

**Test Date-14/04/2023, Due Date-13/04/2024.**

S. No.-2, Plot No.-256,  
Indryaninagar, Bhosari ,  
Pune – 411 026,  
Mobile – 9850600253,8796448299.



P.N. Kulkarni  
B.E. (Mech.) M.B.A.  
Ex. Scientist B.A.R.C.  
Chartered Engineer.

**FORM No. 11 (See Rules 62 and 64)***(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : M/S. SATAV PATIL CRANE SERVICE.
- 2) Address of the Factory : Kesnand Phata, Pune – Nagar Road, Wagholi,  
Tal. – Haveli, Dist. – Pune – 412 207.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Fork Lift  
Reg. No. – MH 12 EB 1574  
Capacity.- 3.0 Ton, ( Please refer load chart before lifting), Make – VOLTAS.  
**Location- On Site.**
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory : Mfg. Year – 2007.
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found:-
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate. : 14/04/2023 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 14/04/2023, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

**Test Date-14/04/2023, Due Date-13/04/2024.**

S. No.-2, Plot No.-256,  
Indryaninagar, Bhosari,  
Pune – 411 026,  
Mobile – 9850600253,8796448299.



P.N. Kulkarni  
B.E. (Mech.) M.B.A  
Ex. Scientist B.A.R.C.  
Chartered Engineer.

**FORM No. 11 (See Rules 62 and 64)***(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)*

- 1) Name of occupier of Factory : ISHTIYAK MUSHTAK SHAIKH.
- 2) Address of the Factory : SMS Colony, Kate Chawl, Dapodi, Pune – 411012.
- 3) A) type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles : Diesel Fork Lift  
Reg. No. – MH 12 EB 1401.  
Chassis No. – B11156690.  
Engine No. – A32523.,  
Capacity.- 3.0 Ton, ( Please refer load chart before lifting), Make – VOLTAS.  
**Location- On Site.**
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory : Mfg. Year – 02/2011.
- 4) Date of each last examinations made under section 28(I) (a) (ii) and 29 (I) (a) (iii) and by whom it was carried out : First time inspection by P.N. Kulkarni
- 5) A) Maintenance: (List of parts, if any, which were inaccessible) Are the order? If not, state what defects have been found:-
- a) Enclosure of hoist way or lift way : Not Applicable
- b) Landing gates and cage gate (s). : Not Applicable
- c) Interlocks on the landing gates and cage gate (s) : Not Applicable
- d) Other gates fastenings : Not Applicable
- e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. : Not Applicable
- f) Overrunning devices : Not Applicable
- g) Suspension ropes or chains and their attachments : Not Applicable
- h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes : Not Applicable
- i) Brakes : Found OK
- j) Work of spur gearing : Not Applicable
- k) Other electrical equipment : Not Applicable
- l) Other parts. : Found OK
- B) (i) Date and number of the certificate relating to any test and examination made under sub-rule (I) of rule 64 together with the name of the person who issued the certificate. : 14/04/2023 by P.N. Kulkarni
- c) (i) Date of annealing or there heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. : Not Applicable
- (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect. : Nil. OK for Use
- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alternations (if any) : Found OK.

I/We certify that on dt. 14/04/2023, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

**Test Date-14/04/2023, Due Date-13/04/2024.**

S. No.-2, Plot No.-256,  
Indryaninagar, Bhosari,  
Pune – 411 026,  
Mobile – 9850600253,8796448299.



P.N. Kulkarni  
B.E. (Mech.) M.B.A  
Ex. Scientist B.A.R.C.  
Chartered Engineer.