

(Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles)

- 1) Name of occupier of Factory
- 2) Address of the Factory
- 3) a) Type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.

M/s: UNDE CRANE SERVICE
CHAKAN, TAL - KHED, DIST - PUHE

Hydraulic mobile crane.
Reg No-MH 14 CM 1112
Capacity- 14 TON.
Make-ESCORT LTD.
Location : On Site.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory.
- 4) Date of each last examinations made under Section 28 (1) (a) (ii) and 29 (1) (a) (iii) and by whom it was carried out.

Mfg year : 2012.
First time tested By P.N.KULKARNI.

- 5) (A) Maintenance : (List of parts, if any, which were inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found :-
 - (a) Enclosure of hoistway or liftway.
 - (b) Landing gates and cage gate (s).
 - (c) Interlocks on the landing gates and cage gate (s).
 - (d) Other gates fastenings
 - (e) Cage and platform and fittings, cage guides, buffers, interior of the hoistway or liftway.
 - (f) Overrunning devices
 - (g) Suspension ropes or chains and their attachments.
 - (h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.
 - (i) Brakes
 - (j) Work of spur gearing.
 - (k) Other electrical equipment.
 - (l) Other parts.

: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable
: Not Applicable

B) Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificate.

: 25/03/2023 By P.N.Kulkarni .
: Not Applicable.

C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out.

: Use only safe working load.

(i) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.

: Found OK.

- 6) Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any)

We certify that on dt. 25/03/2023 I/ We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report of the result.

Next Due date : 24/03/2024.

P. N.Kulkarni & Co.
SUDHA KALASH
Flat No-304, Kalptaru Estate,
Pimple Nilakh, Mobile-9422460662.
e-mail-pnkulkarni_1961@rediffmail.com
AN ISO 9001:2015 CERTIFIED COMPANY.



P. N. Kulkarni
B. E. (Mech) M.B.A.
Ex Scientist B.A.R.C.
Chartered Engineer.