

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Chain Pulley Block on monorail Trolley Cap : 3 Ton, Make : Indef, Loc : Loading Unloading Area
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 05-11-1999
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
	k) Other electrical equipment.	: Not Applicable
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Chain Pulley Block found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11.

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul Ramchandra
DN: cn=IN, st=Maharashtra,
2.5.4.20=0c473cccc798e13a55251a93a975d400ccf
0d1491d1f8b4c0e2077db89bcff3,
postalCode=412114, street=Building NoA3, Flat
No302,Nilay Gat. No 288,Jadhav Wadi,Chikhali
Bk,Chikhali,Mulshi,Pune,
pseudonym=cfb7db2d298f6db669e7ba9abaac0
b, title=8596,
serialNumber=83cee82d1a2ca7351db3429fa26b
7d01bdf34572bc4b3834f6095a7b10add6,
o=Persomal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:21:43 +05'30'

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Chain Pulley Block Cap : 3 Ton, Make : Morris Loc : Shop Floor
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 15-08-2004
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
5C	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Chain Pulley Block found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul Ramchandra
DN: cn=, st=Maharashtra,
2.5.4.20=0c4731ccc798e13a55251a93a975d400
ccfd31491d1f8b4c0fc20f7ab89b4f3,
postalCode=412114, street=Building NoA3, Flat
No302,Nilay Gat No 288,Jadhav Wadi,Chikhali
Bk,Chikhlee,Mulshi,Pune,
pseudonym=cfb7d82d298f66db569e7ba9e8aac
f0b, title=ES96,
serialNumber=83cee82d1a2ca73510b3429f4a2
6b7d018df34572bc4b3834f6095a7b10add6,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:22:02 +05'30'

FORM - 11

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Chain Pulley Block Cap : 3 Ton, Make : Indef Loc : Shop Floor, Sr. No. MH 310200
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 10-10-2004
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
k) Other electrical equipment.	: Not Applicable	
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Chain Pulley Block found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul
Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=0c473ccc798e13a55251a93a975d40
0ccfd1491d1f8b4c0fe20f7db89bcf3,
postalCode=412114, street=Building NoA3,
Flat No302,Nilay Gat No 288,Jadhav
Wadi,Chikhali Bk,Chikhlee,Mulshi,Pune,
pseudonym=cfb7d82d298fc6db669e7ba9aba
acf0b, title=B596,
serialNumber=83cee82d1a2ca7351db3429f4
a26b7d018df34572bc4b3834f6095a7b10add6
, o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:22:15 +05'30'

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Chain Pulley Block Cap : 2 Ton, Make : Bull, Loc : Shop Floor,
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 09-08-2016
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
5C	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Chain Pulley Block found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM – 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=0c473cccc798e13a55251a93a975d400ccf
0d1491d1f8b4c0fe207db89bcff3,
postalCode=412114, street=Building NoA3, Flat
No302, Nilay Gat No 288, Jadhav Wadi, Chikhali
BK, Chikhali, Pune,
pseudonym=cb7d82d298fc6db669e7ba9abaacf0
b, title=8596,
serialNumber=83cee82d1a2ca7351db3429f4a26b
7d018df34572bc4b3834f6095a7b10add6,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:22:30 +05'30'

FORM - 11

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block, MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Chain Pulley Block Cap : 3.15 Ton, Loc : Shop Floor,
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 05-06-2018
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
k) Other electrical equipment.	: Not Applicable	
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Chain Pulley Block found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=0c473cccc798e13a55251a93a975d400c
cf0d1491d1f8b4c0fe207db89bcbf3,
postalCode=412114, street=Building NoA3, Flat
No302,Nilay Gat No 288,Jadhav Wadi,Chikhali
BK,Chikhice,Mulshi,Pune,
pseudonym=#b7d82d298fcd3d669e7ba9abaac
f0b, title=8596,
serialNumber=83cee82d1a2ca77351db3429fa2
6b7d018df34572bc4b3834f6095a7b10add6,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:22:45 +05'30'

FORM - 11

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Hand Pallet Truck Cap : 2 Ton, Make : Local Purchase
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 20-11-2012
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
k) Other electrical equipment.	: Not Applicable	
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Hand Pallet Truck found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person :

Bulkunde
Gokul
Ramchandra

Digitally signed by Bulkunde Gokul Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=0c473cccc798e13a55251a93a975d400
ccfd1491d1f8b4c0fe20f7db89bcff3,
postalCode=412114, street=Building NoA3, Flat
No302, Nilay Gat No 288, Jadhav Wadi, Chikhali
Bk, Chiklee, Mulshi, Pune,
pseudonym=cfb7d82d298fc6db669e7ba9abaac
f0b, title=8596,
serialNumber=83cee82d1a2ca7351db3429fa2
6b7d018d1b4572bc4b3834f6095a7b10add6,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:23:00 +05'30'

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Hand Pallet Truck Cap : 3 Ton, Make : Asmita
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 02-03-2022
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
k) Other electrical equipment.	: Not Applicable	
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Hand Pallet Truck found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM – 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : Bulkunde
Gokul
Ramchandra

Digitally signed by Bulkunde Gokul Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=bc473cccc798e13a55251a93a975d4400c
f0d1491d1fbbfc0fe207db89bcff3,
postalCode=412114, street=Building NoA3, Flat
No 302, Nilay Gat No 288, Jadhav Wadi, Chikhali
Bk, Chikhlee, Mulshi, Pune,
pseudonym=c17d82d298fc6db669e7ba9abaac0
b, title=DS96,
serialNumber=03ccc0281a2e8f3514fb3420f4a2c
b7d018d34522bc4b3834f6095a7b10ad16,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:23:17 +05'30'

FORM – 11

(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F – II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Hand Pallet Truck Cap : 3 Ton, Make : Asmita
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope sand lifting tackles were first taken into use in the factory.	: 11-12-2021
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: 08-06-2022 BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
k) Other electrical equipment.	: Not Applicable	
l) Other parts.	: Not Applicable	
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
5C	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Hand Pallet Truck found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM – 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : Bulkunde
Gokul
Ramchandra

Digitally signed by Bulkunde Gokul Ramchandra
DN: c=IN, st=Maharashtra,
2.5.4.20=0c473ccc798e13a55251a93a975d400c
ef0d1491a1f1f1b4c06v207d0b9bc#3,
postalCode=412114, street=Building NoA3, Flat
No302,Nilay Gat No 28II, Jadhav Wadi,Chikhall
Bk,Chikhlee,Mulshi,Pune,
pseudonym=fb7d62d298fc6db669e7ba9abaacf
0b, title=Q596,
serialNumber=3cee82d1a2caff351db3429f4a2
6b7d016df34572bc4b3834f6095a7b10add6,
o=Personal, en=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:23:51 +05'30'

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

1	Name of the Occupier	: MR MILIND GANESH KELKAR
2	Name and address of the Factory	: M/s. Fine ARC Systems Pvt. Ltd. 21, F - II Block , MIDC, Pimpri, Tal : Haveli, Dist : Pune
3A	Type, Identification numbers and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: Hand Pallet Truck Cap : 3 Ton, Make : Asmita
3B	Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, rope and lifting tackles were first taken into use in the factory.	: 11-12-2021
4	Date of last examinations made under section 28(1)(a)(ii) and 29(1)(a)(iii) and by whom it was carried out.	: First Inspection BY MR GOKUL R. BULKUNDE
5A	Maintenance: (List of parts, if any, which were inaccessible) Are following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:	:
	a) Enclosure of hoist way or lift way.	: Not Applicable
	b) Landing Gates and Cage gate(s).	: Not Applicable
	c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	d) Other gates fastenings.	: Not Applicable
	e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.	: Not Applicable
	f) Overrunning devices.	: Not Applicable
	g) Suspension ropes or chains and their attachments.	: Not Applicable
	h) Safety gear i.e. arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	i) Brakes	: OK
	j) Work of spur gearing.	: Not Applicable
5B	Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificates.	: 01-07-2023 BY MR GOKUL R. BULKUNDE
	i) Date of annealing or their heat treatment of the chain and lifting tackle carried out under sub-rule (5) of Rule 64 and by whom it was carried out.	: Not Applicable
5C	ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: NIL
6	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe working load subject to repairs, renewals or alterations (if any).	: Detailed Visual Inspection and Test has been carried out after test performance above Hand Pallet Truck found in good working condition

I/We certify that on **01-07-2023** I/We thoroughly examined the hoist or lift, lifting machine, ropes and lifting tackles and details of examination/tests carried out is enclosed herewith that the above is a correct report of the result.

FORM - 11
(See Rule 62 & 64)

REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE

Name of Competent Person	MR GOKUL R. BULKUNDE
Qualification	AUTHORIZED COMPETENT PERSON CPC No. MS/DISH/CPC/B-067/2023 CPC Valid up to (Dec. 2025)
Address	SIGMA TECHNO ASSOCIATES, PIMPRI, PUNE-411018.
Test Date / Due Date	01-07-2023 Due Date : 30-06-2024

Signature of Competent Person : **Bulkunde
Gokul
Ramchandra**

Digitally signed by Bulkunde Gokul Ramchandra
DN: cn=IN, st=Maharashtra,
2.5.4.20=0c473ccc798e13a55251a93a975d400ccf0
d1491d1f8b4c0e2070b69bcf3,
postalCode=412114, street=Building NoA1, Flat
No.302,Niley Gat No 288,Jadhav Wadi,Chikhali
Rd,Chikhlee,Mulshi,Pune,
pseudoDn=cf07082d290fc60b669c7ba0abaac0b,
title=ASPM,
serialNumber=83cee82d1a2ca17351db342804a26b7
d018d34572bc8b5b34609547b10ad56,
o=Personal, cn=Bulkunde Gokul Ramchandra
Date: 2023.07.04 13:24:13 +05'30'