



Innovative Industrial Services

Different Needs : One Solution

Flat A1/203, Eklingji Residency, Behind Police Station, Sanand, Ahmedabad: 382110
Mobile No: +91 7874955710 / +91 8128919320, Email: servicesinnovative1@gmail.com

Ref No - IIS / 19-20

Date : 01.05.2024

Insp Date : 01.04.2024

Tool Condition Checksheet

Sr No	Tool Description	Insp Freq	Insp Method	Physical Damage	Electrical Cable	Working Condition	Remark
1	Gas Charging Line	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
2	Copper Tube Cutter	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
3	Screw Driver & Plyer	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
4	Clamp Meter	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
5	Spring Bender	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
6	Vaccum Pump	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
7	Hexa Blade	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
8	Brazing Torch	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
9	Hammer Drill Machine	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use
10	Hand Drill Machine	Once / Quarter	Visual / Use	No Damage	Found OK	Excellent	OK For Use

Note : Inspection Carried out by Internal HVAC Engineer



For, Innovative Industrial Services

Authorised Signatory