

# SAHYADRI CONSTRUCTION

## CHECKLIST

### CRANE FARANA

Name of Project:- *AGSPL DMIC Shendror, Aurangabad,*

Date:- *01/01/23*

Name Of Contractor *Sahyadri construction*

Frequency *-01 month,*

| Sr.no | Particular/Identification No.   | Ok                                  | Not Ok | NA | Remark                                      |
|-------|---|-------------------------------------|--------|----|---|
| 1     | Tower crane should be physically in good condition, free from defects | <input checked="" type="checkbox"/> |        |    | <i>All<br/>Above<br/>points<br/>are ok.</i> |
| 2     | Operator have suitable license/experience certificate                 | <input checked="" type="checkbox"/> |        |    |   |
| 3     | Angle Indicator   | <input checked="" type="checkbox"/> |        |    |   |
| 4     | Load Chart (Name plate SWL board display)                             | <input checked="" type="checkbox"/> |        |    |   |
| 5     | Load Hook and hook Safety Latch                                       | <input checked="" type="checkbox"/> |        |    |   |
| 6     | Condition of boom   | <input checked="" type="checkbox"/> |        |    |   |
| 7     | Leakage in hydraulic  | <input checked="" type="checkbox"/> |        |    |   |
| 8     | Condition Of Slings, Deshaket's, Wire rope.                           | <input checked="" type="checkbox"/> |        |    |   |
| 9     | Lights & Indicator  | <input checked="" type="checkbox"/> |        |    |   |
| 10    | Safe load indicator   | <input checked="" type="checkbox"/> |        |    |   |
| 11    | Out riggers conditions  | <input checked="" type="checkbox"/> |        |    |   |
| 12    | Front Horn  | <input checked="" type="checkbox"/> |        |    |   |
| 13    | Reverse horn  | <input checked="" type="checkbox"/> |        |    |   |
| 14    | Tyre Pressure   | <input checked="" type="checkbox"/> |        |    |   |
| 15    | Crane should be have valid TPI (Form 11)                              | <input checked="" type="checkbox"/> |        |    |   |

Overall Remarks, if any:- *All Above points are ok.*

me & Sign of Safety Officer:  




# SAHYADRI CONSTRUCTION

## CHECKLIST

### Electrical Drill Machine

Name of Project:- *AGSPL Shendra, Aurangabad,*

Location:- *Shendra* Identification No. :-

Date:- *01/01/23*

| Sr.no | Particular   | Ok | Not Ok | NA | Remark                                  |
|-------|--|----|--------|----|---|
| 1     | Body structure is in good condition  | ✓  |        |    | } <i>All points are clear &amp; ok.</i> |
| 2     | Cable has double insulation  | ✓  |        |    |   |
| 3     | Cable and plug are in good condition   | ✓  |        |    |   |
| 4     | Drilling bit should be in good condition                                       | ✓  |        |    |   |
| 5     | Equipment should be free from any defect like broken handle, broken parts etc. | ✓  |        |    |   |
| 6     | Industrial plug top available  | ✓  |        |    |   |
| 7     | Condition and presence of the switch   | ✓  |        |    |   |
| 8     |  |    |        |    |   |
| 9     |  |    |        |    |   |
| 10    |  |    |        |    |   |

Overall Remarks, if any:- *All Above points are ok.*



Signature of Safety Officer:



# SAHYADRI CONSTRUCTION

## CHECKLIST

Grinding Machine

Name of Project:- *Auric Ghendra mada*

Name Of Contractor *Sahyadri construction*


Date:- *01/01/2023*

Frequency *- 01/01/2023*

| Sr.no | Particular/Identification No.          | OK | Not ok |  |  |  |  |  |  |
|-------|--|----|--------|--|--|--|--|--|--|
| 1     | Fore handle without damage.            | ✓  |        |  |  |  |  |  |  |
| 2     | Wheel guard (covering 3/4th area).     | ✓  |        |  |  |  |  |  |  |
| 3     | Grinding wheel without any crack.      | ✓  |        |  |  |  |  |  |  |
| 4     | Rear handles without any damage.       | ✓  |        |  |  |  |  |  |  |
| 5     | Trigger switch without damage.         | ✓  |        |  |  |  |  |  |  |
| 6     | Presence of Switch lock                | ✓  |        |  |  |  |  |  |  |
| 7     | Electric wire without cuts and joints. | ✓  |        |  |  |  |  |  |  |

Note: If OK condition, tick right mark if not OK condition, tick mark cross

Overall Remarks, if any: *All Above points are checked OK.*

  
 Name & Sign of Safety Officer:  
*Sahyadri*  
 Name & Sign of Project Manager/..



# SAHYADRI CONSTRUCTION

## CHECKLIST


### Mobail Tower Crane

Name of Project:- *AGSPL Shendora, Aurangabad.*  
 Location:- *DME Shendora, Aurangabad.* Identification No. :- *01* Date:- *01/01/23*

| Sr.no | Particular   | Ok | Not Ok | NA | Remark                |
|-------|--|----|--------|----|-----------------------|
| 1     | Tower crane should be physically in good condition, free from defects                | ✓  |        |    | <i>All points ok.</i> |
| 2     | Foundation should be provided as per design  |    |        | ✓  |                       |
| 3     | Safe working load should be marked   | ✓  |        |    |                       |
| 4     | Counter weight should be properly fixed.   | ✓  |        |    |                       |
| 5     | Trolley condition should be good   | ✓  |        |    |                       |
| 6     | Limit switch should be provided and its working condition                            | ✓  |        |    |                       |
| 7     | Sling, ropes should be free from defects   | ✓  |        |    |                       |
| 8     | D-shackle should be good condition   | ✓  |        |    |                       |
| 9     | Safety latch should be in hook   | ✓  |        |    |                       |
| 10    | Power cable should be free from damages and connection taken through industrial plug | ✓  |        |    |                       |
| 11    | Operator have suitable license/experience certificate                                | ✓  |        |    |                       |
| 12    | Tower crane should be physically in good condition & should have valid TPI           | ✓  |        |    |                       |
| 13    | Load capacity chart displayed  | ✓  |        |    |                       |
| 14    | Earthing Provision   | ✓  |        |    |                       |
| 15    | Horn   | ✓  |        |    |                       |

Overall Remarks, if any: *All Above points are ok.*

Signature & Sign of Safety Officer:





# SAHYADRI CONSTRUCTION

## CHECKLIST

### BREAKER

Name of Project:- AGSPL Shendra mtpc

Date:- 01/01/23

Name Of Contractor Sahyadri construction

Frequency - 01 month

| Sr.no | Particular/Identification No.   | Ok | Not Ok | NA | Remark                               |
|-------|---|----|--------|----|--------------------------------------|
| 1     | Chisel condition  | ✓  |        |    | All points are ok. & good condition. |
| 2     | Tightness of chisel lock nut  | ✓  |        |    |                                      |
| 3     | Handle without any damage   | ✓  |        |    |                                      |
| 4     | Condition of the body   | ✓  |        |    |                                      |
| 5     | Trigger switch without damage   | ✓  |        |    |                                      |
| 6     | Electric wire without cuts and joints Body earthing in case of metal body | ✓  |        |    |                                      |
| 7     | Power cable properly terminated with gland                                | ✓  |        |    |                                      |
| 8     | Any other points  | ✓  |        |    |                                      |

Overall Remarks, if any:- All Above point are ok.



Signature & Sign of Safety Officer: