#### **GIRISH PAWAR**

B.E., M.B.A. C. Eng. (I), FIV, FICA, M. CIArb, M. Com (RE)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITRATORS
- \* COMPETENT PERSON UNDER FACTORIES/ **EXPLOSIVES ACT**

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/146

DATE: 29/11/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory

: Director

2. Address of the factory

: Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service

X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackles.

- :-\* Description: HYDRAULIC MOBILE CRANE
  - \* Reg.No. MH-20 AY-2375
- :- \* Cap. 12 Ton SWL.
  - \* Make . Escorts Construction Equipment Ltd.
  - \* Chassis No. 1936478017
  - \* Engine No. S433-093550

Inspected at. Location X-195, Kamgar Chowk, MIDC Walui, Aurangabad.

b) Date of construction or reconstruction and the date when the :- 17 Dcc.2007 hoist, lift, lifting machine, chains, ropes and lifting tackles were first

taken in to use in the factory. 4.Date of test examination made under :- Previously tested by us on dt.29/11/2021

Section 28(1) (a) (ii) and 29 (1) (a) (iii)

5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

(a)Enclosure of hoistway or Liftway.

(b) Landing gates and cage gate (s)

Interlocks on the landing gates And cage gates (s)

(d)Other gates fastenings.

(e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway



#### **GIRISH PAWAR**

B.E., M.B.A, C. Eng.(I), FIV, FICA

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ **EXPLOSIVES ACT**

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

DATE: 07/6/2022

REF./GPA/NBM/2022-23/38

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

- 1. Name of occupier of factory
- 2. Address of the factory

Director

Mr. Navnath Bajaba Mutke ( M/s Mutke & Sons Crane Service )

Plot. No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.

- 3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackle.
- :- \* Description : HYDRAULIC MOBILE CRANE
  - \* Reg. No. MH.-20 CU-6757
- -\* Cap. 14 Ton SWL.
- \* Model: Crane F-15
- \*Make . Escorts Construction Equipment Ltd. Ballabgarh, Dist. Faridabad. 121004 Haryana India
- \*Chassis No. 169E038418
- \*Engine No. **E413CDK053403E**

Inspected at. Location Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- :- Dec.2015
- 4.Date of test examination made under :- Previously tested by us on dt.09/06/2021
- Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)
  - Are the following parts of the hoist or lift properly maintained and in good working order? If not state what defects have been found:-
- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- O Interlocks on the landing gates And cage gates (s)
- (d)Other gates fastenings



#### GIRISH PAWAR

B.E., M.B.A, A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL: girish pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/120

DATE: 28/07/2022

### Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory

: Director

2. Address of the factory

: Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- 3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackles.
- :-\* Description : FORK LIFT ASSY.
  - \* Reg. No. MH-20AS-6758
- \* Cap. 3 Ton SWL.
- \* Make . Voltas Ltd. Thane
- \* Chassis No. G11157236
- \*Engine No. A38219

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- :- 3 Jan. 2012
- Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- 4.Date of test examination made under :- Previously tested by us on dt. 28/07/2021

5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

(a)Enclosure of hoistway or Liftway.

(b) Landing gates and cage gate (s)

© Interlocks on the landing gates. And cage gates (s) (d)Other gates fastenings.

(e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway



#### GIRISH PAWAR

B.E., M.B.A. C. Eng. (I), FIV, FICA, M. CIArb, M. Com (RE)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- ARBITRATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/145

DATE: 29/11/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1.Name of occupier of factory

2. Address of the factory

: Director : Mr. Navnath Bajaba Mutke

M/s Mutke & Sons Crane Service

X-195, Kamgar Chowk, MIDC Waluj,

Aurangabad.

3.(a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.

- :-\* Description : HYDRAULIC MOBILE CRANE
- \* Reg. No. MH-20 AY-3216
- \* Cap. 10 Ton SWL.
  - \* Make . Escorts Construction Equipment Ltd.
  - \* Chassis No. 1377349622
- \* Engine No. S433-098025

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains,

ropes and lifting tackles were first taken in to use in the factory.

:- 17/07/2008

4.Date of test examination made under :- Previously tested by us on dt. 29/11/2021 Section 28(1) (a) (ii) and 29 (1) (a) (iii)

5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

(a)Enclosure of hoistway or Liftway.

(b) Landing gates and cage gate (s)

C Interlocks on the landing gates And cage gates (s)

(d)Other gates fastenings.

(e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway

aWar Page 1 of 2

#### **GIRISH PAWAR**

B.E., M.B.A, A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No., 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/116

DATE: 28/07/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

- 1. Name of occupier of factory
- 2. Address of the factory

: Director

Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service

Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.

- 3.(a) Type of Identification number and description of hoist , lift, lifting machine, chains, ropes and lifting tackles.
- :- \* Description : FORK LIFT ASSY.
- \* Reg. No. MH-20BA-3758
- \* Cap. 3 Ton SWL.
- \* Make . Voltas Ltd. Thane.
- \* Chassis No. DVXF 10155799
- \*Engine No. A23442

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- 4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- :- Previously tested by us on dt. 28/07/2021
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible) Are the following parts of the hoist or

lift properly maintained and in good working order? If not, state what defects have been found:-

- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- © Interlocks on the landing gates And cage gates (s)
- (d)Other gates fastenings.
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway

:- 28 Sept.2010



#### **GIRISH PAWAR**

B.E., M.B.A, A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ **EXPLOSIVES ACT**

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/117

DATE: 28/07/2022

# Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

- 1. Name of occupier of factory
- 2. Address of the factory
- : Director
- Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service

Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.


- 3.(a) Type of Identification number and description of hoist lift, lifting machine, chains, ropes and lifting tackles.
- :- \* Description : FORK LIFT ASSY.
  - \* Reg.No. MH-20BA-3657
- \* Cap. 3 Ton SWL.
- \* Make . Voltas Ltd. Thane.
- \* Chassis No. DVXF 10155797
- \*Engine No. A23431

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- 4. Date of test examination made under
- :- 28 Sept.2010
- Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- :- Previously tested by us on dt. 28/07/2021
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- © Interlocks on the landing gates And cage gates (s)
- (d)Other gates fastenings.
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway





#### **GIRISH PAWAR**

B.E., M.B.A, C. Eng. (I), FIV, FICA, M. ClArb, M. Com (RE)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITRATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No.9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/144

DATE:29/11/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1.Name of occupier of factory

2.Address of the factory

: Director

: Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service

X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackles.

- :-\* Description : HYDRAULIC MOBILE CRANE
  - \* Reg. No. MH-20CT-5058
- :- \* Cap. 14 Ton SWL.
  - \* Make . Escorts Construction Equipment Ltd.
  - \* Chassis No. 195B537815
  - \* Engine No. S433-A50828

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.

:- 7- Nov.-2012

4.Date of test examination made under :- Previously tested by us on dt. 29/11/2021 Section 28(1) (a) (ii) and 29 (1) (a) (iii)

5. (Λ) Maintenance: (List of parts, if any ;- Not Applicable

were inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-


(a)Enclosure of hoistway or Liftway.

(b) Landing gates and cage gate (s)

C Interlocks on the landing gates And cage gates (s)

(d)Other gates fastenings.

(e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway





**GIRISH PAWAR** 

B.E., M.B.A. C. Eng. (I), FIV, FICA, M. CIArb, M. Com (RE)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITRATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/147

DATE: 28/11/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory

: Director

2. Address of the factory

tackles.

: Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service

X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting

- :-\* Description : HYDRAULIC MOBILE CRANE \* Reg. No. MH-20 CT-5157
- :- \* Cap. 12 Ton SWL.
  - \* Make . Escorts Construction Equipment Ltd. Faridabad Haryana.
  - \* Chassis No. 193B915722
  - \* Engine No. S433-A48725

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.

:- 19 Nov.2012

4.Date of test examination made under

Section 28(1) (a) (ii) and 29 (1) (a) (iii)

5. (A) Maintenance: (List of parts, if any ;- Not Applicable

were inaccessible) Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

(a)Enclosure of hoistway or Liftway.

(b) Landing gates and cage gate (s)

C Interlocks on the landing gates And cage gates (s)

(d)Other gates fastenings.

(e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway

:- Previously tested by us on dt.21/11/2021



#### **GIRISH PAWAR**

B.E., M.B.A,

A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/119

DATE: 28/07/2022

# Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

- 1. Name of occupier of factory
- 2. Address of the factory
- : Director
- : Mr. Navnath Bajaba Mutke

M/s Mutke & Sons Crane Service

X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- 3.(a) Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting
- :-\* Description : FORK LIFT ASSY.
  - \* Reg.No. MH-20AS-6757
- \* Cap. 3 Ton SWL.
- \* Make . Voltas Ltd. Thane
- \* Chassis No. H11157106
- \*Engine No. A38944

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- :- 3 Jan. 2012
- - Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- 4.Date of test examination made under :- Previously tested by us on dt. 28/07/2021
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- © Interlocks on the landing gates And cage gates (s)
- (d)Other gates fastenings.
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway



# GIRISH PAWAR

B.E., M.B.A, A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITARATORS
- \* COMPETENT PERSON UNDER FACTORIES/ EXPLOSIVES ACT

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No.9892689989

E-MAIL: girish\_pawar2002@yahoo.co.in DATE: 28/07/2022

REF./GPA/M&S CS/2022-23/118

Form No.11

(See Rules 62 and 64) Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles


- 1. Name of occupier of factory
- 2. Address of the factory
- Director
- Mr. Navnath Bajaba Mutke M/s Mutke & Sons Crane Service X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- 3.(a)Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackles.
- :-\* Description : FORK LIFT ASSY.
  - \* Reg.No. MH-20AS-5331
- :- \* Cap. 3 Ton SWL.
  - \* Make . Voltas Industrial Diesel Forklift Truck.
  - \* Chassis No. H11157435
  - \*Engine No. A40948

Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first
- taken in to use in the factory. 4.Date of test examination made under :- Previously tested by us on dt.28/07/2021
- :- 31 Oct. 2011
- Section 28(1) (a) (ii) and 29 (1) (a) (iii)
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- C Interlocks on the landing gates
- And cage gates (s)
- (d)Other gates fastenings.
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway



# **GIRISH PAWAR**

B.E., M.B.A, C. Eng. (I), FIV, FICA, M. CIArb, M. Com (RE)

- \* CHARTERED ENGINEER
- \* GOVT.APPROVED VALUERS
- \* ARBITRATORS
- \* COMPETENT PERSON UNDER FACTORIES/ **EXPLOSIVES ACT**

Office: 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL: girish pawar2002@yahoo.co.in

DATE: 29/11/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1.Name of occupier of factory

REF./GPA/NBM/2022-23/143

2.Address of the factory

: Director

: Mr. Navnath Bajaba Mutke ( M/s Mutke & Sons Crane Service )

Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.

- 3.(a)Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackle.
- :-\* Description : HYDRAULIC MOBILE CRANE
- \* Reg. No. MH.-20 FG-6757
- :-\* Cap. 14 Ton SWL.

:- August .2019

- \* Model: Crane F-15
- \*Make . Escorts Limited (Construction). Ballabgarh, Dist. Faridabad.121004 Haryana India
- \*Chassis No. ECE02169JK0292115
- \*Engine No. **E413CDKG292315E**

Inspected at. Location Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC Area Waluj, Aurangabad.

- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory.
- 4.Date of test examination made under :- Previously tested by us on dt. 29/11/2021 Section 28(1) (a) (ii) and 29 (1) (a) (iii) and
- 5. (A) Maintenance: (List of parts, if any ;- Not Applicable were inaccessible)

Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-

- (a)Enclosure of hoistway or Liftway.
- (b) Landing gates and cage gate (s)
- © Interlocks on the landing gates And cage gates (s)
- (d)Other gates fastenings.
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway



#### **FORM 11**

(See Rule62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles
Maharashtra Factories Rules 1963. Certificate No. 474/ Mutke & Sons Crane Services/D'Shackle

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site At: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad442401.
3.	<ul><li>(a)Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles.</li><li>(b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.</li></ul>	D'Shackle, Make: Damar Sr. No.: 11, 12, 13, 14 (4 Nos.) Maximum Capacity: 9.5T, Jaw Size: 48mm, Pin Dia.: 32mm, Pin Length: 106mm, Shackle Dia: 28mm, Shackle Length: 175mm  Manufacturing Year: Not Available
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	<ul> <li>(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:- <ul> <li>(a) Enclosure of hoist way or lift way.</li> <li>(b) Landing gates and cage gate(s).</li> <li>(c) Interlocks on the landing gates and cage gate(s)</li> <li>(d) Other gates fastenings.</li> <li>(e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.</li> <li>(f) Overrunning devises.</li> <li>(g) Suspension ropes or chains and their attachments.</li> <li>(h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes.</li> <li>(i) Brakes.</li> <li>(j) Work of Spur Gearing</li> <li>(k) Other electrical equipment.</li> <li>(l) Other Parts</li> </ul> </li> <li>(B) Date and number of the certificate relating to any test and examination made under sub-rule(1) of rule 64 together with the name of</li> <li>The person who issued the certificate.</li> <li>(C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out.</li> <li>(ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.</li> </ul>	(A) Not Applicable  (a) Not Applicable (b) Not Applicable (c) Not Applicable (d) Not Applicable (e) Not Applicable (f) Not Applicable (g) Not Applicable (h) Not Applicable (i) Not Applicable (j) Not Applicable (k) Not Applicable (l) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 7.6T In case of any damage in shackle is observed, it Should be immediately removed from use.

I/We certify that on **18.01.2023**, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to **17.01.2024**or change in working height/location whichever occurs earlier



Office Address:

933/A/265 Chitanvispura, Shivaji Nagar, Behind Kendra Vidhyalaya, Near Pritam Kirana Stors, Nagpur – 440032 Contact No: +91 77210 10291.



Amol Zalke BE (MECH),

Competent Authority for Safety and Health MS/DISG/CPC/Z-001/2022

### **FORM 11**

(See Rule62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles Maharashtra Factories Rules 1963. Certificate No. 0473/ Mutke & Sons /Nylon Sling.

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site at: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad.
3.	(a)Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles.	Nylon Sling, Make: Duero. Sr. No: 01/23/138 (1 no.) Maximum Capacity: 6T , Sling Length:6 mtr, Colour: Orange
	(b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.	Manufacturing Year: 04.1.2023
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	<ul> <li>(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:- <ul> <li>(a) Enclosure of hoist way or lift way.</li> <li>(b) Landing gates and cage gate(s).</li> <li>(c) Interlocks on the landing gates and cage gate(s)</li> <li>(d) Other gates fastenings.</li> <li>(e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.</li> <li>(f) Overrunning devises.</li> <li>(g) Suspension ropes or chains and their attachments.</li> <li>(h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes.</li> <li>(i) Brakes.</li> <li>(j) Work of Spur Gearing</li> <li>(k) Other electrical equipment.</li> <li>(l) Other Parts</li> </ul> </li> <li>(B) Date and number of the certificate relating to any test and examination made under sub- rule(1) of rule 64 together with the name of</li> <li>The person who issued the certificate.</li> </ul>	(A) Not Applicable  (b) Not Applicable (c) Not Applicable (d) Not Applicable (e) Not Applicable (f) Not Applicable (g) Not Applicable (h) Not Applicable (i) Not Applicable (j) Not Applicable (j) Not Applicable (k) Not Applicable (k) Not Applicable (l) Not Applicable
	(C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out.  (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	(C) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 4.8 T In case of any damage in Sling is observed, it Should be immediately removed from use.

I/We certify that on 18.01.2023, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to 17.07.2023 or change in working height/location whichever occurs earlier

Absolute Safety

Office Address

Chitanvispura, Shivaji Nagar, Mahal, Nagpur 440032. Contact No: +91 93095 64790.



Amol Zalke
BE (MECH), PGDTD CAD-CAE
Competent Authority for Safety and Health
MS/DISG/CPC/Z-001/2022

# **FORM 11**

(See Rule62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles Maharashtra Factories Rules 1963. Certificate No. 0472/ Mutke & Sons /Nylon Sling.

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site at: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad.
3.	(a)Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles.	Nylon Sling, Make: Duero. Sr. No: 01/23/139 (1 no.) Maximum Capacity: 6T , Sling Length:6 mtr, Colour: Orange
	(b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.	Manufacturing Year: 04.1.2023
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	<ul> <li>(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:-</li> <li>(a) Enclosure of hoist way or lift way.</li> </ul>	(A) Not Applicable  (a) Not Applicable
	<ul> <li>(b) Landing gates and cage gate(s).</li> <li>(c) Interlocks on the landing gates and cage gate(s)</li> <li>(d) Other gates fastenings.</li> <li>(e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way.</li> <li>(f) Overrunning devises.</li> </ul>	<ul><li>(b) Not Applicable</li><li>(c) Not Applicable</li><li>(d) Not Applicable</li><li>(e) Not Applicable</li><li>(f) Not Applicable</li></ul>
	<ul><li>(g) Suspension ropes or chains and their attachments.</li><li>(h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes.</li><li>(i) Brakes.</li></ul>	(g) Not Applicable (h) Not Applicable  (i) Not Applicable
	(j) Work of Spur Gearing (k) Other electrical equipment.	(j) Not Applicable (k) Not Applicable
	<ul> <li>(I) Other Parts</li> <li>(B) Date and number of the certificate relating to any test and examination made under sub-rule(1) of rule 64 together with the name of</li> <li>The person who issued the certificate.</li> </ul>	(I) Not Applicable (B) Not Applicable
	<ul> <li>(C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out.</li> <li>(ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.</li> </ul>	(C) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 4.8 T In case of any damage in Sling is observed, it Should be immediately removed from use.

I/We certify that on **18.01.2023**, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to **17.07.2023** or change in working height/location whichever occurs earlier

Absolute Safety

Office Address

Chitanvispura, Shivaji Nagar, Mahal, Nagpur 440032. Contact No: +91 93095 64790.



BE (MECH), PGDTD CAD-CAE Competent Authority for Safety and Health MS/DISG/CPC/Z-001/2022



# **MUTKE & SONS**



Labour Supply Machinery, Loading - Unloading Contractor

Kamgar Chowk, X-195, MIDC Waluj, Aurangabad - 431 136.

☎: E-mail ID - mutkeandsons6757@gmail.com Mobile: 9822312063

Ref.

# **EXPERANCE LETTER**

To,

**Endurance Technology** 

K-226/2 midc waluj Aurangabad

Sub:- DECLARATION OF EXPERANCE LATTER

Respected sir,

I '/ We MUTKE AND SON'S Crane Services Through is Authorised Signatory Mr. Navnath Bajaba Mutke Vendor Code 206547, Hereby Conform That; Our Labour Experance for the Period 15 (Fifteen Years)

MUTKE AND SON'S

FOR MUTKE & SONS

PROPRIETOR

Proprietor

# A.Y. 2020-2021

Name

: MUTKE NAVNATH BAJABA

Father's Name: BAJABA MUTKE

Address

: PLOT NO. X-195

KAMGAR CHOWK

MIDC AREA

WALUJ., AURANGABAD - 431 136

Previous Year: 2019-2020

PAN

: AGVPM 9130 E

Status

: Individual

Date of Birth : 20-Dec-1970

Aadhaar No. : 7466 4262 0830

#### Resident

Statement of In	come			
		Rs.	Rs.	Rs.
Profits and gains of Business or Profession				
Business: Presumptive profits u/s 44AD	1		11,48,378	
Income chargeable under the head "Business and Profession"				11,48,378
Income from other sources				
Interest income	2		2,462	
Dividends	3		0	2,462
Income chargeable under the head "other sources"				2,402
Gross Total Income			-	11,50,840
Deductions under Chapter VI-A				
80TTA: Interest on Saving a/c			2,462	
Investment u/s 80C, CCC, CCD				
Life insurance premium		2,16,074		
PF contribution		1,00,000		
Deduction subject to ceiling u/s 80CCE			1,50,000	1,52,462
Deduction in respect of payments from 01-Apr-20 to 31-Jul-20 For Sch.DI)	4	0		
otal Income				9,98,37
otal income rounded off u/s 288A				9,98,38
ax on total income				1,12,17
dd: Cess				4,48
ax with cess				1,16,66
et Tax				1,16,66
os	5		1,55,371	
tal prepaid taxes				1,55,3
lance Tax				-38,70
e u/s 234F				10,0
fund Due				28,7
hadula 4				
hedule 1		Turnavia	,	
sumptive Profits-u/s 44AD		Turnover	9	6 Prof

Presumptive Profits-u/s 44AD	Turnover / Receipts	%	Profits
Income from Mutke and Sons	1,27,29,725	9.02	11,48,378



TDS TDS claimed Gross receipt

# Schedule 2

Interest income (other than NSC/KVP interest)

Name of the Bank

Interest on Savings a/c (80TTA)

Bank of Baroda

Interest

2,462

850

Schedule 3

Particulars

Dividends exempt u/s 10(34) or taxable u/s 115BBDA

Dividend Received

Dividends exempt u/s 10(34)

Amount

850

Schedule 4

Schedule, 5

TDS as per Form 16A

Deductor, TAN

	deducted in	current year	offered
A B Brothers, TAN- MUMA23366A	12,890	12,890	6,44,500
Ajanta Pharma Limited, TAN- MUMA08396D	211	211	21,100
Badve Autocomps Private Limited, TAN- NSKB01164C	441	441	44,100
Badve Engineering Limited, TAN- NSKB01165D	580	580	58,000
Badve Engineering Limited, TAN- NSKB04139C	30,485	30,485	30,48,500
Bajaj Auto Limited, TAN- PNEB05807E	13,612	13,612	13,61,200
Balkrishna Industries Limited, TAN- MUMB14660C	18,188	18,188	9,09,346
Blg Parekh Logistics Private Limited, TAN- MUMB18765F	23	23	2,250
Blg Parekh Logistics Private Limited, TAN- MUMB18765F	230	230	11,500
Cg Power And Industrial Solutions Limited, TAN- NSKC01129C	30	30	3,000
Endress And Hauser (india) Automation Instrumentation Private Limited, TAN- NSKE01351A	2,543	2,543	1,27,150
Endurance Technologies Limited, TAN- NSKE00384G	10,999	10,999	10,97,546
Eximius Infra Tech Solutions Llp, TAN- PNEE04669A	4,137	4,137	4,13,700
Garware Polyester Limited, TAN- NSKG01359B	372	372	18,600
Om Logistics Ltd., TAN- DELO01316A	93	93	8,400
Ray Engineering Limited, TAN- MUMR20598E	2,311	2,311	1,15,550
Rekha Madhusudan Sharma, TAN- NSKR06657A	413	413	41,200
Sanjeev Autoparts Manufactures Private Limited, TAN-NSKS06887G	25,256	25,256	25,25,582
Shantdeep Metals Private Limited, TAN- NSKS13066E	1,020	1,020	1,02,000
Varroc, Engineering Limited, TAN- NSKV01249D	4,695	4,695	4,69,298
Total	1,28,529	1,28,529	1,10,22,522
Tay collected at agures			

Tax collected at source



Collector & TAN	TCS	TCS claimed	Expenditure
	collected	in current year	as per 26AS
Auritech Construction Equipment Pvt Ltd, TAN- MUMA14482G	26,842	26,842	26,84,158
Grand Total	1,55,371	1,55,371	
Income with full exemption			
<u>Income</u>	Section	Amount	
Dividend income	10(34)	850	
Total exempt income		850	



73,269

# A.Y. 2021-2022

Name

: NAVNATH BAJABA MUTKE

Father's Name: BAJABA MUTKE

Address

: PLOT NO. X-195

KAMGAR CHOWK

MIDC AREA

WALUJ., AURANGABAD - 431 136

Previous Year: 2020-2021

PAN

: AGVPM 9130 E

Status

: Individual

Date of Birth : 20-Dec-1970

Aadhaar No. : 7466 4262 0830

Total prepaid taxes

Statement of Ir	come			
		Rs.	Rs.	Rs.
Profits and gains of Business or Profession				
Business: Presumptive profits u/s 44AD	1		7,49,775	
Income chargeable under the head "Business and Profession"				7,49,775
Capital Gains				
Long-term Capital gain from Auto-classification schedule			6,014	
Gain from securities	4	1	22,187	
Income chargeable under the head "Capital gains"				28,201
Income from other sources				
Interest income	2		570	
Income chargeable under the head "other sources"				570
Gross Total Income			-	7,78,546
Deductions under Chapter VI-A				
80TTA: Interest on Saving a/c			570	
avestment u/s 80C, CCC, CCD				
Life insurance premium		90,842		
PF contribution		1,50,000		
eduction subject to ceiling u/s 80CCE		_	1,50,000	1,50,570
otal Income				6,27,976
otal income rounded off u/s 288A				6,27,980
		Income	Tax	
Income taxable at normal rates		5,99,779	32,456	
Short-term capital gain taxable @15%		22,187	3,328	
Long-term capital gain				
Taxable @ 10%				
112A - STT paid shares/units		6,014	0	
x on total income				35,7
d: Cess				1,4
with cess				37,2
Tax				37,2
S	3		73,269	



Balance	Гах
Fee u/s 2	34F
Pofund I	2110

-36,054 5,000 31,050

#### Schedule 1

P	resumpti	ve P	rofits-u	1/5 4	4AD
	Income	from	Mutke	and	Sons

Turnover / Receipts	%	Profits	
64.09.680	11.7	7,49,775	

TDS TDS claimed Gross receipt

# Schedule 2

Interest income (other than NSC/KVP interest)

Name of the Bank	Interest
Interest on Savings a/c (80TTA)	
Bank of Baroda	570

# Schedule 3

TDS as per Form 16A Deductor, TAN

	deducted in curren		nt year offered	
A B Brothers, TAN- MUMA23366A	9,712	9,712	6,47,485	
Advent Engg. (p) Ltd., TAN- MUMA20106C	2,260	2,260	3,01,350	
Ajanta Pharma Limited, TAN- MUMA08396D	368	368	42,400	
Badve Autocomps Private Limited, TAN- NSKB01164C	467	467	62,267	
Badve Engineering Limited, TAN- NSKB04139C	1,665	1,665	2,22,000	
Bajaj Auto Limited, TAN- PNEB05807E	4,213	4,213	5,56,401	
Balkrishna Industries Limited, TAN- MUMB14660C	22,436	22,436	14,75,942	
Blg Parekh Logistics Private Limited, TAN- MUMB18765F	38	38	2,500	
Endress And Hauser (india) Automation Instrumentation	303	303	20,033	
Private Limited, TAN- NSKE01351A Endurance Technologies Limited, TAN- NSKE00384G	9,552	9,552	12,68,611	
Eximius Infra Tech Solutions Llp, TAN- PNEE04669A	962	962	1,28,266	
Om Logistics Ltd., TAN- DELO01316A	6	6	600	
Ray Engineering Private Limited, TAN- MUMR20598E	11,489	11,489	7,43,832	
Sanjeev Autoparts Manufactures Private Limited, TAN-	6,066	6,066	7,36,664	
NSKS06887G Shantdeep Metals Private Limited, TAN- NSKS13066E	1,265	1,265	1,26,500	
Sunil H Nagarhalli, TAN- PNES23186C	1,361	1,361	90,508	
Varroc Engineering Limited, TAN- NSKV01249D	1,062	1,062	1,41,505	
Varroc Engineering Limited, TAN- NSKV01528C	44	44	5,832	
	73,269	73,269	65,72,696	
Total Total				

# Income with full exemption

<u>Income</u>

Section	Amount
	THE RESERVE OF THE PARTY OF THE



Interest Received on Public Provident Fund
Total exempt income

10(11) 1,30,222 1,30,222

Bank A/c for Refund: ICICI Bank 004405007656 IFSC: ICIC0000044

Date: 23-Mar-2022

Place: AURANGABAD

[ NAVNATH BAJABA MUTKE ]