

GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A.,
C. Eng. (I), FIV, FICA,
M. CI Arb, M. Com (RE)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/146

DATE : 29/11/2022

Form No.11
(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj,
Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **HYDRAULIC MOBILE CRANE**
* Reg.No. **MH-20 AY-2375**
* Cap. 12 Ton SWL.
* Make . Escorts Construction Equipment Ltd.
* Chassis No. **1936478017**
* Engine No. **S433-093550**
Inspected at. Location X-195. Kamgar Chowk, MIDC Waluj,
Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 17 Dec.2007
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt.29/11/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- © Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



**GIRISH PAWAR
& ASSOCIATE**

GIRISH PAWAR

B.E., M.B.A,
C. Eng.(I),FIV, FICA

- * CHARTERED ENGINEER
- * GOVT. APPROVED VALUERS
- * ARBITRATORS
- * COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/NBM/2022-23/38

DATE : 07/6/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

- 1.Name of occupier of factory : Director
- 2.Address of the factory : **Mr. Navnath Bajaba Mutke**
(M/s Mutke & Sons Crane Service)
Plot. No. X-195,Kamgar Chowk, Near Truck Terminal MIDC
Area Waluj, Aurangabad.
- 3.(a)Type of Identification number and description of hoist ,lift, lifting machine, chains, ropes and lifting tackle. :-* Description : **HYDRAULIC MOBILE CRANE**
* Reg. No. **MH.-20 CU-6757**
:-* Cap. 14 Ton SWL.
* Model: Crane F-15
*Make . Escorts Construction Equipment Ltd.
Ballabgarh, Dist. Faridabad.121004 Haryana India
*Chassis No. **169E038418**
*Engine No. **E413CDK053403E**
Inspected at. Location Plot.No. X-195,Kamgar Chowk, Near
Truck Terminal MIDC Area Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- Dec.2015
- 4.Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt.09/06/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found:-
- (a)Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- © Interlocks on the landing gates And cage gates (s) :- --
- (d)Other gates fastenings. :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A,
A.M.I.E (I), FIV, FICA, M. CI Arb (UK)

- * CHARTERED ENGINEER
- * GOVT. APPROVED VALUERS
- * ARBITRATORS
- * COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/120

DATE : 28/07/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **FORK LIFT ASSY.**
* Reg. No. **MH-20AS-6758**
* Cap. 3 Ton SWL.
* Make . Voltas Ltd. Thane
* Chassis No. **G11157236**
* Engine No. **A38219**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 3 Jan. 2012
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 28/07/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- (c) Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A.,
C. Eng. (I), FIV, FICA,
M. CI Arb, M. Com (RE)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/145

DATE : 29/11/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj,
Aurangabad.
- 3.(a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **HYDRAULIC MOBILE CRANE**
* Reg. No. **MH-20 AY-3216**
* Cap. 10 Ton SWL.
* Make . Escorts Construction Equipment Ltd.
* Chassis No. **1377349622**
* Engine No. **S433-098025**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj,
Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 17/07/2008
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 29/11/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- © Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A,
A.M.I.E (I), FIV, FICA, M. CIArb (UK)

- * CHARTERED ENGINEER
- * GOVT. APPROVED VALUERS
- * ARBITRATORS
- * COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No., 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/116

DATE : 28/07/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC
Area Waluj, Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **FORK LIFT ASSY.**
* Reg. No. **MH-20BA-3758**
* Cap. 3 Ton SWL.
* Make . Voltas Ltd. Thane.
* Chassis No. **DVXF 10155799**
* Engine No. **A23442**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- **28 Sept. 2010**
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- **Previously tested by us on dt. 28/07/2021**
5. (A) Maintenance: (List of parts, if any were inaccessible) :- **Not Applicable**
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
 - (a) Enclosure of hoistway or Liftway. :- --
 - (b) Landing gates and cage gate (s) :- --
 - © Interlocks on the landing gates And cage gates (s) :- --
 - (d) Other gates fastenings. :- --
 - (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A,
A.M.I.E (I), FIV, FICA, M. CIArb (UK)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/117

DATE : 28/07/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC
Area Waluj, Aurangabad.
- 3.(a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **FORK LIFT ASSY.**
* Reg.No. **MH-20BA-3657**
* Cap. 3 Ton SWL.
* Make . Voltas Ltd. Thane.
* Chassis No. **DVXF 10155797**
* Engine No. **A23431**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 28 Sept.2010
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 28/07/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- (c) Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



**GIRISH PAWAR
& ASSOCIATE**

GIRISH PAWAR

B.E., M.B.A.,
C. Eng. (I), FIV, FICA,
M. CI Arb, M. Com (RE)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/144

DATE : 29/11/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj,
Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles :- * Description : **HYDRAULIC MOBILE CRANE**
* Reg. No. **MH-20CT-5058**
* Cap. 14 Ton SWL.
* Make . Escorts Construction Equipment Ltd.
* Chassis No. **195B537815**
* Engine No. **S433-A50828**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj,
Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 7- Nov.-2012
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 29/11/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- (c) Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A.,
C. Eng. (I), FIV, FICA,
M. CI Arb, M. Com (RE)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/M&S CS/2022-23/147

DATE : 28/11/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **HYDRAULIC MOBILE CRANE**
* Reg. No. **MH-20 CT-5157**
* Cap. 12 Ton SWL.
* Make . Escorts Construction Equipment Ltd.
Faridabad Haryana.
* Chassis No. **193B915722**
* Engine No. **S433-A48725**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 19 Nov.2012
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt.21/11/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- (c) Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A,
A.M.I.E (I), FIV, FICA, M. CI Arb (UK)

- * CHARTERED ENGINEER
- * GOVT. APPROVED VALUERS
- * ARBITRATORS
- * COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPAM&S CS/2022-23/119

DATE : 28/07/2022

Form No.11 (See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **FORK LIFT ASSY.**
* Reg.No. **MH-20AS-6757**
* Cap. 3 Ton SWL.
* Make . Voltas Ltd. Thane
* Chassis No. **H11157106**
* Engine No. **A38944**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 3 Jan. 2012
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 28/07/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- © Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway :- --



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A,
A.M.I.E (I), FIV, FICA, M. CI Arb (UK)

- * CHARTERED ENGINEER
- * GOVT. APPROVED VALUERS
- * ARBITRATORS
- * COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.
Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

DATE : 28/07/2022

REF./GPA/M&S CS/2022-23/118

Form No. 11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
M/s Mutke & Sons Crane Service
X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
3. (a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles. :- * Description : **FORK LIFT ASSY.**
* Reg. No. **MH-20AS-5331**
* Cap. 3 Ton SWL.
* Make . Voltas Industrial Diesel Forklift Truck.
* Chassis No. **H11157435**
* Engine No. **A40948**
Inspected at. Location X-195, Kamgar Chowk, MIDC Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- 31 Oct. 2011
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 28/07/2021
5. (A) Maintenance: (List of parts, if any were inaccessible) :- Not Applicable
Are the following parts of the hoist or lift properly maintained and in good working order? If not, state what defects have been found:-
 - (a) Enclosure of hoistway or Liftway. :-
 - (b) Landing gates and cage gate (s) :-
 - (c) Interlocks on the landing gates And cage gates (s) :-
 - (d) Other gates fastenings. :-
 - (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway liftway :-



GIRISH PAWAR & ASSOCIATE

GIRISH PAWAR

B.E., M.B.A.,
C. Eng. (I), FIV, FICA,
M. CI Arb, M. Com (RE)

* CHARTERED ENGINEER
* GOVT. APPROVED VALUERS
* ARBITRATORS
* COMPETENT PERSON UNDER FACTORIES/
EXPLOSIVES ACT

Office : 61, BANSILAL NAGAR, AURANGABAD 431 005.

Mobile No. 9892689989

E-MAIL : girish_pawar2002@yahoo.co.in

REF./GPA/NBM/2022-23/143

DATE : 29/11/2022

Form No.11

(See Rules 62 and 64)

Report of examination of hoist, lift, lifting machine, chains, ropes and lifting tackles

1. Name of occupier of factory : Director
2. Address of the factory : **Mr. Navnath Bajaba Mutke**
(M/s Mutke & Sons Crane Service)
Plot.No. X-195, Kamgar Chowk, Near Truck Terminal MIDC
Area Waluj, Aurangabad.
- 3.(a) Type of Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackle. :-* Description : **HYDRAULIC MOBILE CRANE**
* Reg. No. **MH.-20 FG-6757**
:-* Cap. 14 Ton SWL.
* Model: Crane F-15
* Make . Escorts Limited (Construction).
Ballabgarh, Dist. Faridabad.121004 Haryana India
*Chassis No. **ECE02169JK0292115**
*Engine No. **E413CDKG292315E**
Inspected at. Location Plot.No. X-195, Kamgar Chowk, Near
Truck Terminal MIDC Area Waluj, Aurangabad.
- b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken in to use in the factory. :- August .2019
4. Date of test examination made under Section 28(1) (a) (ii) and 29 (1) (a) (iii) and :- Previously tested by us on dt. 29/11/2021
5. (A) Maintenance: (List of parts, if any ; - Not Applicable were inaccessible)
- Are the following parts of the hoist or lift properly maintained and in good working order ? If not, state what defects have been found:-
- (a) Enclosure of hoistway or Liftway. :- --
- (b) Landing gates and cage gate (s) :- --
- (c) Interlocks on the landing gates And cage gates (s) :- --
- (d) Other gates fastenings. :- --
- (e) Cage and platform and fittings, Cages guides, buffers, interior of the hoistway or liftway :- --



FORM 11

(See Rule 62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles

Maharashtra Factories Rules 1963. Certificate No. 474/ Mutke & Sons Crane Services/D'Shackle

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site At: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad 442401.
3.	(a) Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles. (b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.	D'Shackle, Make: Damar Sr. No.: 11, 12, 13, 14 (4 Nos.) Maximum Capacity: 9.5T, Jaw Size: 48mm, Pin Dia.: 32mm, Pin Length: 106mm, Shackle Dia: 28mm, Shackle Length: 175mm Manufacturing Year: Not Available
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:- (a) Enclosure of hoist way or lift way. (b) Landing gates and cage gate(s). (c) Interlocks on the landing gates and cage gate(s) (d) Other gates fastenings. (e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. (f) Overrunning devices. (g) Suspension ropes or chains and their attachments. (h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes. (i) Brakes. (j) Work of Spur Gearing (k) Other electrical equipment. (l) Other Parts (B) Date and number of the certificate relating to any test and examination made under sub-rule(1) of rule 64 together with the name of The person who issued the certificate. (C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	(A) Not Applicable (a) Not Applicable (b) Not Applicable (c) Not Applicable (d) Not Applicable (e) Not Applicable (f) Not Applicable (g) Not Applicable (h) Not Applicable (i) Not Applicable (j) Not Applicable (k) Not Applicable (l) Not Applicable (B) Not Applicable (C) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 7.6T In case of any damage in shackle is observed, it Should be immediately removed from use.

I/We certify that on **18.01.2023**, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to **17.01.2024** or change in working height/location whichever occurs earlier

**Absolute Safety****Office Address:**

933/A/265 Chitanvispura, Shivaji Nagar,
Behind Kendra Vidhyalaya, Near Pritam Kirana Stors,
Nagpur – 440032 Contact No: +91 77210 10291.

**Amol Zalke**
BE (MECH),Competent Authority for Safety and Health
MS/DISH/CPC/Z-001/2022

FORM 11

(See Rule 62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles
Maharashtra Factories Rules 1963. Certificate No. 0473/ Mutke & Sons /Nylon Sling.

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site at: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad.
3.	(a) Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles. (b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.	Nylon Sling, Make: Duero. Sr. No: 01/23/138 (1 no.) Maximum Capacity: 6T , Sling Length: 6 mtr, Colour: Orange Manufacturing Year: 04.1.2023
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:- (a) Enclosure of hoist way or lift way. (b) Landing gates and cage gate(s). (c) Interlocks on the landing gates and cage gate(s) (d) Other gates fastenings. (e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. (f) Overrunning devices. (g) Suspension ropes or chains and their attachments. (h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes. (i) Brakes. (j) Work of Spur Gearing (k) Other electrical equipment. (l) Other Parts (B) Date and number of the certificate relating to any test and examination made under sub-rule(1) of rule 64 together with the name of The person who issued the certificate. (C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	(A) Not Applicable (a) Not Applicable (b) Not Applicable (c) Not Applicable (d) Not Applicable (e) Not Applicable (f) Not Applicable (g) Not Applicable (h) Not Applicable (i) Not Applicable (j) Not Applicable (k) Not Applicable (l) Not Applicable (B) Not Applicable (C) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 4.8 T In case of any damage in Sling is observed, it Should be immediately removed from use.

I/We certify that on **18.01.2023**, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to **17.07.2023** or change in working height/location whichever occurs earlier

**Absolute Safety****Office Address**

Chitanvispura, Shivaji Nagar,
Mahal, Nagpur 440032.
Contact No: +91 93095 64790.



Amol Zalke
BE (MECH), PGDTD CAD-CAE
Competent Authority for Safety and Health
MS/DISG/CPC/Z-001/2022

FORM 11

(See Rule62 and 64)

Report of Examination of Hoists, Lift, Lifting Machine, Chains, Ropes and Lifting Tackles
Maharashtra Factories Rules 1963. Certificate No. 0472/ Mutke & Sons /Nylon Sling.

1.	Name of the Occupier:	M/S Mutke & Sons Crane Services
2.	Name and Address of Factory	Site at: Kamgar Chowk, X-195, MIDC Waluj, Aurangabad.
3.	(a) Type, Identification number and description of hoist, lift, lifting machine, chains, ropes, and lifting tackles. (b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, ropes and lifting tackles were first taken into use in the factory.	Nylon Sling, Make: Duero. Sr. No: 01/23/139 (1 no.) Maximum Capacity: 6T, Sling Length: 6 mtr, Colour: Orange Manufacturing Year: 04.1.2023
4.	Date of each examination made under Section 28(1)(a)(ii) and Sec. 29(1)(a)(iii) and by whom it was carried out.	First Time Tested by us on: 18.01.2023
5.	(A) Maintenance: (List of parts, if any, which were inaccessible) Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:- (a) Enclosure of hoist way or lift way. (b) Landing gates and cage gate(s). (c) Interlocks on the landing gates and cage gate(s) (d) Other gates fastenings. (e) Cage and platform and fittings, cage guides, buffers, interior of the hoist way or lift way. (f) Overrunning devices. (g) Suspension ropes or chains and their attachments. (h) Safety gear, i.e. arrangements for preventing fall of platform or cage brakes. (i) Brakes. (j) Work of Spur Gearing (k) Other electrical equipment. (l) Other Parts (B) Date and number of the certificate relating to any test and examination made under sub-rule(1) of rule 64 together with the name of The person who issued the certificate. (C) (i) Date of annealing or other heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out. (ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	(A) Not Applicable (a) Not Applicable (b) Not Applicable (c) Not Applicable (d) Not Applicable (e) Not Applicable (f) Not Applicable (g) Not Applicable (h) Not Applicable (i) Not Applicable (j) Not Applicable (k) Not Applicable (l) Not Applicable (B) Not Applicable (C) Not Applicable
6.	Repairs, renewals or alterations (if any) required and the period within which they should be executed and Maximum safe working load subject to repairs, renewals or alternations (if any)	Recommended SWL: 4.8 T In case of any damage in Sling is observed, it Should be immediately removed from use.

I/We certify that on **18.01.2023**, I/We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/tests carried out is enclosed herewith that the above is a correct report of the result. Certificate Valid up to **17.07.2023** or change in working height/location whichever occurs earlier

**Absolute Safety****Office Address**

Chitanvispura, Shivaji Nagar,
Mahal, Nagpur 440032.
Contact No: +91 93095 64790.



Amol Zalke
BE (MECH), PGDTD CAD-CAE
Competent Authority for Safety and Health
MS/DISG/CPC/Z-001/2022