

FORM - 11
REPORT OF EXAMINATION OF HOIST, LIFT, LIFTING MACHINE, CHAINS, ROPES AND LIFTING TACKLE
 (See Rule 62- 64)

1)	Name of the Occupier	: M/s. MAP ALLOYS (Plant I)
2)	Address Of Factory	: A/3 , GAT NO : 357/72 , KHARABWADI WAGHJAINAGAR , CHAKAN PUNE - 410 501
3)	(PCMC) Type Identification number and description of hoist, lift, lifting machine, chains, ropes and lifting tackles.	: SINGLE GIRDER BOX TYPE EOT CRANE . ID No : MA/PI/EOT /01 , Rope Size : 16 mm X 2 Fall Make : — , Capacity : 5.0 Ton Location : Shop Floor , Plant No - 01
	(b) Date of construction or reconstruction and the date when the hoist, lift, lifting machine, chains, ropes and lifting tackles were first taken into use in the factory.	: As Per Factory Record.
4)	Date of last examinations made under section 28 (1) (a) (ii) and 29 (1) (a) (iii) and by whom it was carried out.	: As On 13.07.2021 By Mr. Somnath B Mane , CPC No - M056/2021
5)	(A) Maintenance: (List of parts, if any, which were inaccessible). Are the following parts of the hoist of lift properly maintained and in good working order? If not, state what defects have been found:-	: Not Applicable
	(a) Enclosure of hoist way or lifeway.	: Not Applicable
	(b) Landing gates and cage gate(s).	: Not Applicable
	(c) Interlocks on the landing gates and cage gate(s).	: Not Applicable
	(d) Other gates fastenings.	: Not Applicable
	(e) Cage and platform and fittings, cage guides buffers, interior of the hoistway or liftway.	: Not Applicable
	(f) Overrunning devices	: Operating Properly & Found O. K
	(g) Suspension ropes or chains and their attachments.	: Found Satisfactory
	(h) Safety gear, i.e arrangements for preventing fall of platform or cage brakes.	: Not Applicable
	(i) Brakes.	: Operating Properly & Found O.K.
	(j) Work of spur gearing.	: Operating Properly & Found O.K
	(k) Other electrical equipment.	: Found O.K.
	(l) Other Parts	: Found Satisfactory
	(B) Date and number of the certificate relating to any test and examination made under sub-rule (1) of rule 64 together with the name of the person who issued the certificate.	: As On 12.07.2022 By Somnath B Mane CPC NO : MS/DISH/CPC/M-056/2021 (DEC-2023)
	(C) (i) Date of annealing or the heat treatment of the chain and lifting tackle carried out under sub-rule (5) of rule 64 and by whom it was carried out	: Not Applicable
	(ii) Particulars of any defect found at any such examination or after annealing and affecting the safe working load and of the steps taken to remedy such defect.	: N.A
	Repairs, renewals or alterations (if any) required and the period within which they should be executed and maximum safe Working load subject to repairs, renewals or alterations (if any)	: Detailed Visual Inspection & Test Has Been Carried Out After Test Performance Eot Crane Found In Good Operating Condition.

I/We certify that on 12.07.2022 / We thoroughly examined the hoist, lift, lifting machine, ropes and lifting tackles and details of examinations/test carried out is enclosed herewith that the above is a correct report the result



Next Due : 11.07.2023

Mr. Somnath B. Mane

Government Of Maharashtra (Dish) Authorized Competent Person As Per Factory Act 1948
 CPC NO: MS/DISH/CPC/M-056/2021 (DEC-23)