

MAHAGANPATI ASSOCIATE

Gat No. 887, Khedikar Vasti, Ranjagaon Ganapti, Shirur, Pune 412209

Mob.: 1860526639/9850180739, Email: - mahaganpatiang@gmail.com

GSTIN No.: 27LCWPK4064P1ZD State 27- Maharashtra

Date:

Declaration

- 1) Are the tools and equipment used in good working condition? : Yes, all tools are working in good condition.
- 2) Do the tools and equipment comply with standards such as ISI Mark / Energy Efficient 5 star rating guidelines? Yes, All tools and equipment's are with standards such as ISI Mark / Energy Efficient 5 star rating guidelines
- 3) Is the holding handle of equipment in good condition? Yes, holding handle of equipment is in good condition
- 4) Are all plants and equipment compliant with the safety requirements? (including not damaged cables, no loose connections, equipped with 3 pin top). Yes, all plants and equipment compliant with the safety requirements.
- 5) Do contract employees have correct licenses / certificates to operate the plants and equipment? There are no contract employees

For Mahaganpati Associate

Pawan Deshmukh

Production Manager

Ranjangaon

Date: 05/03/2023

EQUIPMENT DAILY CHECKLIST AND SAFETY INSPECTION FORM

NOTE: This form is not to be used for inspections of mobile/overhead cranes, powered industrial trucks, or aerial lifts. For inspections of such equipment, use FBP-OS-PRO-00025-F05 (for mobile/overhead cranes), FBP-OS-PRO-00057-F01 (for powered industrial trucks), or FBP-WM-PRO-00061-F07 (for Section 1

Location / Project: Furnace Contact Name: KANIF KOLHE				Contractor: FBP or					
									Section 2 - Ch
Cutting Machine Pug Machine \(\sigma\) Loader					Manufacturer MAHAGANPATI ASSOCAITE				
☑ Machine ☑ Miling Machine ☑ Welding Machine ☑ Dozer				Model Number					
Tractor	r (specify)	specify)							
Report all iteMark N/A for	k $()$ mark in the box to ir ox where Problem is four ms in need of repair to th items which do not apply	e Supervisor		ete and is s		ssary.	7		
	rk as Directed Above								
Inspection Item / Day of Week		April	May	June	lulu	14110			
	Worker Badge Number		c.y	Julie	July	AUG			
40	Worker Initials					1			
	Date	~							
191	Hour Meter Reading	~							
Structural Damage – none apparent		~	1 1						
Tires / Tracks – condition acceptable		/							
Load Chart – available/readable		/							
Glass / Mirrors – clean/clear; unobstructed		~							
Electrical Connections (generators)		V	. 0						
Hydraulic Hoses – good condition/no leaks									
Check Valves - functional		/							
ubrication – adequate amount		V				, , , , , , , , , , , , , , , , , , ,			
luid Levels – adequate amounts/no leaks		V						- /	
Engine Oil - level/appearance good		~				1			
Cooling Water – adequate amount/no leaks		V							
Operating Manual - available		~							
ire Extinguisher – present, charged, dated		V							
eat Belts – functional/latch properly		/							
perating Controls - functional		/							
orn / Gauges - functional		V							
ghts and Reflectors – clean/functional		1							
indshield Wipers - functional		/	-02						
r Systems - functional		V							
eering Mechanism -	functional	V							
akes - functional		~							
ckup Alarm - function		V							
Switch (if available) - functional		1							
ll-off Truck Cable – r	no single strand etching; clamps tight	./							

Cherred By Pawan peshmuren Production mornages Date. 02/05/2023

Ramandesur Ranjangaon