

Identification mark

Part name :- OUTER TUBE RH/LH (KONA)

Problem description :-

OK PART



THREADING M6X1-6H OK PART



ENSURE THAT, THREADING M6X1-6H OPERATION COMPLETED , THEN YELLOW" MARK" AS SHOWN.